


MC34



Installation Instructions



MN-005698-01EN-P Rev. A




Zebra Technologies | 3 Overlook Point | Lincolnshire, IL 60069 USA
zebra.com

The Zebra wordmark and logo are trademarks of Zebra Technologies Corp., registered in many jurisdictions worldwide. All other trademarks are the property of their respective owners.
©2026 Zebra Technologies Corp. and/or its affiliates.

1 Cup Removal




CAUTION-ESD: This rework activity must be performed by a qualified technician or engineer in an ESD safe workstation. The technician or engineer must wear a grounded ESD strap.




1. Remove the AC power from the cradle.
2. Using a Phillips screwdriver, remove the screw securing the charge-only cup to the cradle.

1 Cup Removal (continued)




3. Slide the charge-only cup forward and lift.




4. Disconnect the charge-only cup cable from the connector.

2 Cup Installation




5. Connect the new charge-only cup cable to the connector.



6. Align the new charge-only cup with the cradle and slide the charge only cup back.

2 Cup Installation (continued)



7. Using a Phillips screwdriver, secure the new charge-only cup to the cradle with a screw.

? Support and Information



Contact Zebra
about your product.
zebra.com/contact



View Quick Answers
and Knowledge Base.
zebra.com/knowledge



Learn about product
patent information.
ip.zebra.com



Join Community Connection
of Zebra users and ambassadors.
zebra.com/supportcommunity

