Release Notes - RS507 - Partial data loss when RS507 configured in HID mode with Android devices - SPR 28122

Introduction

SPR28122 - Partial data loss when RS507 configured in HID mode and paired to any Android device (TC55, MC40).

Description

Default Inter character HID Keyboard Keystroke Delay was resulting in Partial data loss when RS507 configured in HID mode and paired to any Android device (TC55, MC40).

Added the following configurable Inter character HID Keyboard Keystroke Delays in RS507 firmware to fix the Partial data loss,

1. No Delay (0 ms)
2. Medium Delay (20 ms)
3. Long Delay (40 ms)

Contents

Part number	Description	SW File
PAAACS00-005-R06	RS507 FW Product Code	PAAACS00-005-R06D0.DAT

Device Compatibility

This HotFix CFE Package software release has been approved for use with the following Zebra devices.

Device	Operating System
RS507	Micro OS-II

Installation Requirements

- RS507 scanner.

- Computer running Windows 7 or Windows XP with BT support.

- PC tool Application RS507PCTOOL000103.exe.

Installation Instructions

- Upgrade latest firmware "PAAACS00-005-R06D0.DAT to RS507 scanner using "PC tool installation" through Bluetooth stack.

- Refer "HID Keyboard Keystroke Delay.docx" for configuring RS507 Inter character HID Keyboard Keystroke Delays (0ms or 20ms or 40ms).

- To upgrade latest firmware, pleases refer chapter '7' in page no [7 - 38] of "RS507 Hands-Free Imager Product Reference Guide".

Part Number and Release Date

N/A

April, 2016