Release Notes – MC3190 CE 6.0 Japanese Hotfix OS v60.37.25

Introduction

SPR33002 – Fonts will resize itself after activating the taskbar when taskbar is set to autohide

This Hot Fix OS v60.37.25 is based on BSP v06.37.13

Description

Resolved an issue wherein fonts are resizing itself after activating the taskbar by updating an image 3100c60BjpUC603725.zip

Contents

3100c60BjpUC603725.zip - OSUpdate Package for MC31 CE devices including Clean Application

Device Compatibility

This HotFix OS Package software release has been approved for use with the following Zebra devices.

Device	Operating System	BSP Version
MC3190	CE 6.0	Japanese v06.37.13

Installation Requirements

MC3190 device must contain a released version of CE 6.0

Installation Instructions

1. Unzip the "3100c60BjpUC603725.zip" files and copy its content to the \Temp folder.

2. Place the device to be upgraded on A/C power supply.

3. Navigate to the \temp\OSUpdate folder and invoke the 3100c60Bjp_TEMP shortcut.

4. The update will take about 3-4 minutes to complete. Please do not remove the device

   from A/C power during this time.

OR

1. Unzip the "3100c60BjpUC603725.zip" files and copy its content to the \Storage Card

   folder.

2. Place the SD card in the device to be upgraded.

3. Place the device to be upgraded on A/C power supply.

4. Navigate to the \Storage Card\OSUpdate and invoke the 3100c60Bjp_SD shortcut.

5. The update will take about 3-4 minutes to complete. Please do not remove the device

   from A/C power during this time.

Part Number and Release Date

N/A

November, 2017