Release Notes – WT41N0 CE 7.0 Chinese Traditional Hotfix OS v64.57.06

Introduction

SPR33867/32707 – Unable to display Chinese characters in Dropdown or in combo list box options when Chinese page is browsed.

This Hot Fix OS v64.57.06 is based on BSP v04.57.05

Description

Resolved an issue wherein Chinese fonts are not displaying on IE browser when using dropdown and combo list by updating an image 41X0BctUC645706.zip

Contents

41X0BctUC645706.zip - OSUpdate Package for WT41N0 CE devices including Clean Application

Device Compatibility

This HotFix OS Package software release has been approved for use with the following Zebra devices.

Device	Operating System	BSP Version
WT41N0	CE 7.0	v04.57.05

Note: This release is applicable for Chinese Traditional OS only.

Installation Requirements

WT41N0 device must contain a released version of CE 7.0

Installation Instructions

1. Unzip the "41X0BctUC645706.zip" files and copy its content to the \Temp folder.
2. Place the device to be upgraded on A/C power supply.
3. Navigate to the \temp\OSUpdate folder and invoke the 41X0c70Bct_TEMP.lnk shortcut.
4. The update will take about 3-4 minutes to complete. Please do not remove the device from A/C power during this time.

Part Number and Release Date

N/A

January 2018