Release Notes - MC2100 CE 6.0 Rev D1 Core - 04.34.0130

Introduction

   From the sales floor to the backroom, the Symbol MC2100 mobile computer has what it takes to affordably automate the capture of inventory data right at the point of work. Leveraging Symbol's Mobility Platform Architecture 2.0, the MC2100 offers plenty of processing power, industry-leading data capture capabilities, rugged design, superior ergonomics, flexible data capture options, plus centralized management. Support for Symbol's RhoElements application development platform allows you to create cross-platform applications that work on different mobile computers with different operating systems. MC2100 is available in Wireless LAN (802.11b/g/n) and Batch configuration

Description

General Enhancements in 04.34.0130

-   **NA**

SPR Fixes:

* SPR29121 - Resolved MC21XX SE4500DL Scanner sku face the "No hairline" issue.

Contents

1. 2100c60AenUP043430.zip - OS Update Package v04.34.30 Software (English)
2. 2100c60AenAB043430.apf - AirBeam Package without clean Application.
3. 2100c60AenAC043430.apf - AirBeam Package with clean Application.
4. 2100c60AenOS043430.hex - OS Image v04.34.30 (English)

Device Compatibility

This software release has been approved for use with the following Symbol devices.

Device	Operating System
MC2100	Windows CE 6.0 Core
MC2180	Windows CE 6.0 Core

Installation Requirements

MC2100 device must contain a released version of CE 6.0 Core Software.

Installation Instructions

Update through \Storage Card
- Unzip 2100c60AenUP043430.zip file and copy its contents (**OSUpdate** folder) to the root folder on SD card.
- Insert the SD card in the device to be updated.
- Place the device to be updated on A/C power supply.
- Run **2100c60Aen_SD** shortcut from **\Storage Card\OSUpdate** folder to start the update process.

Update through \Application
- Unzip 2100c60AenUP043430.zip file and copy its content (**OSUpdate** folder) to the **\Application** folder.
- Place the device to be updated on A/C power supply.
- Run **2100c60Aen_App** shortcut from **\Application\OSUpdate** folder to start the update process.

Notes:
- Keep the device in AC Power during the update process.
- Updating through Temp folder is not supported in MC2100 due to RAM space constraints.
- While using Application partition update method, Application data will be kept intact and OSUpdate folder will also remain after completing the OS Update process.

Part Number and Release Date

2100c60AenUP043430
2100c60AenAB043430
2100c60AenAC043430
2100c60AenOS043430

May, 2016