Release Notes – MC92N0 CE 7.0 Chinese Simplified Hotfix OS v66.57.23 – SPR33838

Introduction

SPR33838 – Unable to display Chinese characters in Dropdown or in combo list box options when Chinese page is browsed.

This Chinese Simplified Hotfix OS v66.57.23 is based on BSP v06.57.22

Description

Resolved an issue wherein Chinese fonts are not displaying on IE browser when using dropdown and combo list by updating an image 92N0c70BcpUC665723.

Contents

92N0c70BcpUC665723.zip – OS Update Package with Clean Application.

Device Compatibility

This Hotfix Package software release has been approved for use with the following Zebra devices.

Device	Operating System	BSP Version
MC92N0	CE 7.0	v06.57.22

Note: This release is applicable for Chinese Simplified OS only.

Installation Requirements

MC92N0 device must contain a released version of CE 7.0

Installation Instructions

1. Unzip the "92N0c70BcpUC665723.zip" file and copy its content to the \Temp folder.
2. Place the device to be upgraded on A/C power supply.
3. Navigate to the \Temp\OSUpdate folder and invoke the 92N0c70Ben_TEMP shortcut.
4. The update will take about 3-4 minutes to complete. Please do not remove the device from A/C power during this time.

OR

1. Unzip the "92N0c70BcpUC665723.zip" file and copy its content to the \Storage Card folder.
2. Place the SD card in the device to be upgraded.
3. Place the device to be upgraded on A/C power supply.
4. Navigate to the \Storage Card\OSUpdate and invoke the 92N0c70Ben_SD shortcut.
5. The update will take about 3-4 minutes to complete. Please do not remove the device from A/C power during this time.

Part Number and Release Date

N/A

February 2018