SB1 OS Image v02.01.36

Introduction

The SB1 is a brand new category of mobile device which employers can give to every retail associate. This truly smart badge is full of the features every associate needs to deliver the best customer experience, with the connectivity needed to keep them productive, every minute of every day. The badges each associate wears can allow associates to: access task lists; accept tasks and acknowledge completion; scan a bar code to check price and inventory; and connect via push-to-talk (PTT) with other workers carrying practically any other PTT-enabled mobile device in use in the store. The result is a powerful always-connected workforce that can always access the people and information they need to maximize productivity and exceed customers' expectations on every visit.

Description

1. Fusion Software X_2.01.0.0.054R
2. Team Express version 1.1.63
3. Shell version 2.8.3
4. AirBeam Client v07.08.42
5. RD Client v07.08.42

Release Notes

v02.01.36

Features/Enhancements

- Added support for all new SB1 Integrated Audio SKU (a.k.a. SB1-IAS)
- Standalone Reboot Feature.
- Standalone weekly re-boot is enabled by default to improve memory performance of device.
- Notification to user on accidental suspend of device.
- Improved Wi-Fi performance in low coverage areas.
- More accurate signal strength indication.

Fixes
-
- Improved overall stability in various areas (Boot-Loader, Display, Image Processing, Audio).
- Fixed few blank screen issues in wireless, PTT Express and Settings after coldboot
- Shell Application have control to choose first SIP mode as Alpha or Numeric
- Shell Applications have a control of decimal in SIP for Currency fields.
- Shell application can launch SIP keypad on Text field automatically without clicking.
- During page transitions a hour glass will be displayed instead of white screen while waiting for a response from remote server.
- Barcode scanner enabled after device being idle in badge mode.

Note:
- **Make sure that you remove all shell configurations setting from your SB1 "userdrive" before updating your SB1 device to new OS version.**
- **Applications developed using the Software Development Toolkit v0.7 will not be compatible with OS v02.01.36. Software Development Toolkit v1.4 should be used with OS v02.01.36.**

Contents

1. TSDxc60AenAB020136.APF – A package file for deployment using AirBeam.
2. TSDxc60AenSF020136.ZIP – Additional support package files for deployment using AirBeam.

Device Compatibility

This software release has been approved for use with the following Symbol devices.

Device	Operating System
SB1	Windows CE 6.0

Installation Requirements

- SB1 device must contain a released version of Windows CE 6.0 Software

Installation Instructions

- Please refer to "Image Update Procedure.doc" in TSDxc60AenSF020136.ZIP

Part Number and Release Date

TSDxc60AenAB020136.APF
TSDxc60AenSF020136.ZIP
March 31, 2014