Release Notes - SB1 CE6.0 - BSP v03.01.45 - PTT Displays Incorrect Language In Configuration - SPR 27338

Introduction

SPR 27338- In SB1 device, PTT (Push To Talk) displays incorrect language in configuration.

Description

This fix resolves the issue seen in SPR 27338 wherein PTT (Push To Talk) displays incorrect language in configuration.

Contents

SPR27338.apf

Device Compatibility

This software release has been approved for use with the following Zebra devices,

Device	Operating System
SB1	CE 6.0

Installation Requirements

SB1 flashed with OEM Version v03.01.45

Installation Instructions

For NORMAL installation of the PATCH:

1. Connect device to PC using ActiveSync. To make the SB1 device connectable through ActiveSync, first deploy the "ActiveSyncEnable.apf " package file which is part of the "Software Development Toolkit v2.4 for SB1" available on support central.

2. Once SB1 is connected to PC through ActiveSync, extract contents of the "SPR27338.apf " file and copy to "\Application" folder.

3. Do a terminal reboot by pressing and holding the front trigger and home keys simultaneously.

For MSP or REMOTE installation of the PATCH:

1. Upload the "SPR27338.apf " package into MSP server.

2. Create a bundle using the "SPR27338.apf " package.

3. Create a staging profile using "SPR27338.apf " bundle.

4. Generate PDF barcode.

5. Scan barcode using RD Client utility from device to deploy the package.

5. Once the package is successfully deployed on the device, terminal will do a reboot.

Part Number and Release Date

N/A
July 2015