Release Notes - <TC55 KitKat Localization Release SW V2.52.04>

Introduction

TC55 is a ruggedized device based on Android for the enterprise market that blends the capabilities of a smart phone with those of a traditional enterprise PDA.
TC55 has a number of enterprise-grade features, including a touch-screen that can be used with gloves, support for stylus input for signatures, barcode capture capability and IP67 rating for dust and water protection.

It also features Zebra Extensions (MX) to make the Android operating system more enterprise ready, with security enhancements and hooks for device management tools, and is designed for a longer lifecycle than the typical smart phone.
TC55 is designed in response to customer feedback from using consumer-grade smart phones in the workplace, especially with the bring-your-own-device (BYOD) trend, where employees use their own choice of device for work.

With TC55 the workers can capture practically any type of data — from bar codes and signatures to photos, videos and NFC — improving on the job efficiency and customer service. The screen is optimized for Enterprise viewing, helping ensure the battery lasts a full shift.
And with a drop, tumble and environmental sealing specification you can count on, it has the durability required to serve your field workers for years.

This SW release contains TC55 Android KitKat Rebranded SW version offering new advanced features, increasing operation performance for the customer satisfaction.

Description

1. Android KitKat 4.4.3
2. Kernel 3.4.0
3. DataWedge v 3.1.10
4. Scanning Framework v5.9.0
5. MX.v4.2_4.3-4
6. WLAN FUSION_QA_1.02.0.0.020
7. RIL 1.0.9
8. Modem 20015326.43
9. MSP v07.08.85
10. SOTI client v12.0.0 Build 1049

11. StageNow v 2.0.1.1302
12. SimulScan v1.9
13. EMDK 3.1.19

New Features in this Release

1. Android Version KitKat 4.4.3

2. Rebranded SW

3. StageNow

4. SimulScan

5. 2D Imager SE4710 support (per SKU)

6. AppGallery Version 2.0.8.6

7. Languages SKUs supported (can be ordered as a default out of box):
   - UK English
   - US English
   - French
   - Italian
   - German
   - Spanish
   - Brazilian Portuguese
   - Traditional Chinese
   - Simplified Chinese

Contents

1. T55N0KXXVRUEN25204.zip – TC55 KK OS Recovery Update package
2. T55N0KXXVAUEN25204.apf– TC55 KK OS Airbeam package for MSP deployment
3. T55N0KXVR1PEN25204.zip - TC55 KK RevB Rebranded logos Recovery package for upgrade from TC55 JB to TC55 KK
4. T55N0KXVA1PEN25204.apf - TC55 KK RevB Rebranded logos Airbeam package for upgrade from TC55 JB to TC55 KK
5. TC55KKFCCWLNV07.zip - WLAN Region File FCC
6. TC55KKETSIWLNV07.zip - WLAN Region File ETSI
7. TC55KKFCCWLNV07.apf - WLAN Region File FCC for MSP deployment
8. TC55KKETSIWLNV07.apf - WLAN Region File ETSI for MSP deployment

Device Compatibility

This software release has been approved for use with the following devices

SKUs supported:
TC55BH-KJ11ES
TC55BH-KJ11EE
TC55BH-KJ11ES-NS
TC55BH-KJ11EE-NS

TC55AH-KJ11ES
TC55AH-KJ11EE
TC55AH-KJ11ES-BL
TC55AH-KJ11EE-BL
TC55BH-K011ES
TC55BH-K011EE
TC55BH-KC11ES
TC55BH-KC11EE
TC55BH-K011ES-NS
TC55BH-K011EE-NS
TC55BH-KC11ES-NS
TC55BH-KC11EE-NS
TC55AH-K011ES
TC55AH-K011EE
TC55AH-KC11ES
TC55AH-KC11EE
TC55AH-K011ES-BL
TC55AH-K011EE-BL
TC55AH-KC11ES-BL
TC55AH-KC11EE-BL
TC55AH-KJ11ES-ET
TC55AH-KJ11EE-ET
TC55BH-KJ11ES-TW
TC55BH-KJ11EE-TW
TC55AH-KC11ES-ET
TC55AH-KC11EE-ET
TC55AH-K011ES-ET
TC55AH-K011EE-ET
TC55BH-KC11ES-TW
TC55BH-KC11EE-TW
TC55BH-K011ES-TW
TC55BH-K011EE-TW
TC55BH-KJ11JS-NS
TC55BH-KJ11JE-NS
TC55BH-KC11JS-NS
TC55BH-KC11JE-NS
TC55BH-K011KS-NS
TC55BH-K011KE-NS
TC55BH-KC11KS-NS
TC55BH-KC11KE-NS
TC55BH-KJ11KS-NS
TC55BH-KJ11KE-NS
TC55BH-KJ11CS-NS
TC55BH-KJ11CE-NS
TC55BH-KJ11MS-NS
TC55BH-KJ11ME-NS
TC55BH-K011CS-NS
TC55BH-K011CE-NS
TC55BH-K011MS-NS
TC55BH-K011ME-NS
TC55BH-KC11CS-NS
TC55BH-KC11CE-NS
TC55BH-KC11MS-NS
TC55BH-KC11ME-NS

Installation Requirements

This SW is intended for the TC55 device

Installation Instructions

Please note that installed applications will not be preserved in upgrade from TC55 **JB** to TC55 **KK**.

Please note that once you have upgraded you device to TC55 KK, you cannot downgrade back to TC55 **JB**.

1. T55N0KXXVRUEN25204.zip – TC55 KK OS Recovery Update package
   - Connect the USB cable from your PC to the device and enable USB mass storage mode on the device.
   - On your PC you should see an internal and external USB mass storage drive (SD card) appears in the File Explore and copy the recovery update zip file to any storage.
   - Press and hold on the device the Power button, Scan/Action button and Vol+ until the screen is turned OFF
   - Release the Power and Scan/Action buttons and continue to hold Vol+ button
   - The device should enter to Recovery update mode
   - Release Vol+.
   - Click on Vol+ or Vol- to navigate and select appropriated storage
   - Click on on Scan/Action button to select the option
   - Click on Vol+ or Vol- to navigate to the recovery update zip file
   - Click on on Scan/Action button to select the recovery update zip file
   - Reboot the device
2. T55N0KXVR1PEN25204.zip - TC55 KK RevB Rebranded logos Recovery package for upgrade from TC55 JB to TC55 KK
3. WLAN Region file Recovery update per Country Region – see the table below (not required for TC55 KitKat devices out of factory)

Country Group (Region)	Country Codes	WLAN Region File
USA,	US,	
Canada,	CA,	
Puerto Rico,	PR,	
American Virgin Island,	VI,	
Anguilla,	AI,	
Cayman Islands,	KY,	
Guam,	GU,	TC55KK**FCC**WLNV07.zip
Mariana Islands,	MP,	
Dutch Antilles,	AN,	
Curacao,	CW,	
Bonaire, Saint Eustatius and Saba,	BQ,	
St Maarten,	SX,	
Taiwan,	TW,	
Europe	AT, BE, BG, CY, CZ, DK, EE, FI, FR, DE, GR, HU, IS, IE, IT, LV, LI, LT, LU, MT, NL, NO, PL, PT, RO, SK, SI, ES, SE, CH, GB	

(w/ France)		
South Africa,	ZA,	
United Arab Emirates,	AE,	
Saudi Arabia,	SA,	
Turkey,	TR,	
Falkland Islands,	FK,	
French Guiana,	GF,	
Guadeloupe,	GP,	
Martinique,	MQ,	
Belarus,	BY,	
Macedonia	MK,	
Montenegro,	ME,	
Serbia,	RS,	
Croatia,	HR,	
Japan,	JP,	
Australia,	AU,	
New Zealand,	NZ,	
Christmas Island,	CX,	
Niue Island,	NU,	
Norfolk Island,	NF,	
Russia,	RU,	
Nicaragua,	NI,	
Paraguay,	PY,	
Peru,	PE,	
Philippines,	PH,	
Thailand,	TH,	
Trinidad&Tobago,	TT,	
Uruguay,	UY,	
Kazakhstan,	KZ,	
Argentina,	AR,	
Brazil,	BR,	TC55KK**ETSI**WLNV07.zip
Colombia,	CO,	
Costa Rica,	CR,	
Dominican Republic,	DO,	
El Salvador,	SV,	
Ecuador,	EC,	
Hong Kong,	HK,	
Sri Lanka,	LK,	
Singapore,	SG,	
Chile,	CL,	
India,	IN,	

Mexico,	MX,	
Venezuela,	VE,	
Barbados,	BB,	
Panama,	PA,	
China	CN,	
Lebanon,	LB,	
Malaysia,	MY,	
Ukraine,	UA,	
Israel,	IL,	
Tunisia,	TN ,	
Egypt,	EG,	
Morocco,	MA,	
South Korea,	KR,	
Vietnam,	VN,	
Indonesia,	ID,	
Bolivia,	BO,	
British Virgin Islands,	VG,	
Guyana,	GY,	
Guatemala,	GT,	
Honduras,	HN,	
Jamaica,	JM,	
Algeria,	DZ,	
Nigeria,	NG,	
Kenya,	KE,	
Pakistan,	PK,	

4. MSP OS package update

Please refer Mobility Service Platform deployment guide for instruction for the deployment of the following files:

1. TC55 KK OS Airbeam package
2. TC55 KK RevB Rebranded logos Airbeam package
3. WLAN Region Airbeam file

Notes

Please note that installed applications will not be preserved in upgrade from TC55 JB to TC55 KK.

Part Number and Release Date

1. T55N0KXXVRUEN25204
2. T55N0KXXVAUEN25204
3. TC55KKFCCWLNV07
4. TC55KKETSIWLNV07
5. TC55KKFCCWLNV07
6. TC55KKETSIWLNV07

7. T55N0KXVR1PEN25204
8. T55N0KXVR2PEN25204

May, 2015
-