MC17 OPERATING SYSTEM BSP 04.35.14 - HOTFIX CFE 1.0 RELEASE NOTES

DESCRIPTION

This patch is to fix an issue on MC17 units that have poor display contrast, which leads to not being able to differentiate between similar colors.

This issue is only seen on some MC17 units with a TX07D04VM display.

DEVICE COMPATIBILITY

This software release has been approved for use with the following Symbol devices.

Device	Operating System
MC17	Windows CE 5.0

INSTALLATION REQUIREMENTS

· Windows CE 5.0
· BSP 04.35.14

INSTALLATION INSTRUCTIONS

1. Copy the selected cab file on to any location on the device.

2. Double click on the cab file to start the installation process.

3. Press the 'Ok' button, and the new driver should install.

4. Cold boot the unit to load the new driver

5. If using the cab that auto cold boots, the device will proceed to cold boot after installing the cab

PART NUMBER AND RELEASE DATE

March 21, 2013