



Motion Computing Software Release Note

Name	Atheros 802.11 Vista
File Name	Atheros_WLAN_v7_6_1_162_Vista.zip
Release Date	February 3, 2009
This Version	7.6.1.162
Replaces Version	All previous versions
Intended Users	Motion LE1700 & C5/F5 users
Intended Product	Motion LE1700 & C5/F5 Tablet PCs only
Supported Operating System	Windows Vista (all versions except Windows Vista Home Basic)

Fixes in this Release

- Resolves issue with Main/Aux antenna switch operation
- Resolves issue with intermittent failure of adhoc connect after resume from S3
- Resolves issue with roaming operation when reconnecting to the same AP
- Resolves issue with Cisco AP background sequence number reset
- Resolves issue with Statistics reporting

What's New In This Release

- None

Known Issues and Limitations

- None

Installation and Configuration Instructions

To install this version update, perform the following steps:

1. Download **Atheros_WLAN_v7_6_1_162_Vista.zip**
2. Select your Tablet model and corresponding operating system
3. In the **Wireless Driver** section, click **Atheros WLAN v7.6.1.162**.
4. In the File Download window, click **Save** to download the Atheros file (Atheros_WLAN_v7_6_1_162_Vista.zip) to the directory of your choice.
5. Unzip the file to a location on your local drive.
6. Double-click **setup.exe** in the **Install_CD** folder and follow the prompts.

Licensing

Refer to your applicable end-user licensing agreement for usage terms.