

---

# Release Notes - VC80 Windows 7 Software Package

---

## Contents

---

[Description](#)

[Improvements](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Downloadable Software included in this Release](#)

## Description

---

The VC80 Software Package included 2 software components:

- Embedded Controller firmware
- BIOS

### **Embedded Controller firmware – version 01.03.18**

- The Embedded Controller manages several lower level functions of the VC80
  - Enabling the power supply at boot time
  - Communication with features like the UPS battery, accelerometer and the on-board heaters

### **BIOS – version 01.03.15**

- VC80 Basic **Input Output** System. The BIOS primary role is to load the operating system on the VC80

## Improvements

---

### **Embedded Controller** firmware version 01.03.18

- SPRs - 32634, 34665, 34377, 34355, 34869 – VC80 fails to power ON with external power for a dead battery case.
- SPR 34869: VC80 fails to power on with LED remains green and OS doesn't load.
- Added a system wake from sleep when battery is low (<9%).
- Bezel “keyboard” key is mapped to ENTER key (simplify EC firmware loading)
- Auto load firmware in EUFI shell with “Startup.nsh” script name

### **BIOS** – version 01.03.15

- Updated BIOS package includes fix for Spectre and Meltdown Security Vulnerability
- Auto load firmware in EUFI shell with “Startup.nsh” script name

## Device Compatibility

---

This release is compatible with all VC80 Windows 7 hardware SKUs.

**Note: User must install VC Control Panel Installer image (01.02.00) before installing VC80 Software Package v01.03.00 for Windows 7 OS. Download the Control Panel Installer image from Portal ([Link](#))**

## Installation Requirements

---

- USB flash drive of size 4GB and above
- **VC80 Windows 7 Maintenance Release 2 (01.02.00)**

## Installation Instructions

---

### **Embedded Controller firmware:**

- Refer to the “VC80\_Win7\_Embedded\_Controller\_Firmware\_Update\_Procedure\_v10” included inside 80X0W7XENCF010318.zip of VC80 Software Package.

### **BIOS:**

- Refer to the “VC80\_Win7\_BIOS\_Update\_Procedure\_v10” included inside 80X0W7XENBS010315.zip of VC80 Software Package.

## Downloadable Software Included in this Release

---

File	Description
80X0W7XENZP010300.zip	VC80 Software Package v01.03.00 for Windows 7

Last Revised: October 2018