

Release Notes – Zebra ET8X Tablet Software

ET8X BIOS A07 and Embedded Controller E07 Combined Firmware

Highlights

This BIOS/EC FW combined image rev. 07 is intended for ET8X family of products and is compatible with all existing SKUs and all Windows 10 and Windows 11 OS images.

Software Packages

| Package Name | Description | Release Date |
|--------------------------|---|--------------|
| ET8X_BIOS_A07_EC_E07.zip | BIOS and Embedded Controller combined image | 02/10/2023 |

Version Information

Below Table contains product-specific software component revisions

| Component / Description | Version |
|--|------------------|
| BIOS | A07 |
| Embedded Controller Firmware | EC 7.0 |
| Intel Graphics Output Protocol Driver | 17.0.1071 |
| Intel Management Engine firmware | 15.0.35.1951 |
| Intel BIOS Microcode | 0x806C1 Ver.0x9A |
| Intel Integrated Sensor Hub Controller | 5.4.1.4457 |
| TBT NVM Version | 43.0 |

Device Support

The ET8X products supported in this release are all existing SKUs of ET80A, ET85B and ET85C.

New Features

• None.



Resolved Issues

- SPR48069 Can't flash BIOS due to BitLocker SSD encryption detection error.
- SPR46870 After out of the carrier coverage area, the WWAN occasionally has issue to reconnect back to the network.
- SPR48233 Some systems are not recognizing the WWAN radio.
- Pre-Boot BitLocker PIN software onscreen keyboard layout was not complete.
- After multiple restarts, the NMEA GPS port stopped working.

Usage Notes

To apply an image:

- 1. Extract *.exe file from the package.
- 2. Run the *.exe file on the device.

Known Constraints

None

Important Links

- Zebra Techdocs
- Developer Portal
- ET80 Support Page



Revision History

| Rev | Description | Date |
|-----|--------------------------------|--------------------|
| 1.0 | Initial release | September 13, 2022 |
| 1.1 | Moved Known Constrains section | November 16, 2022 |