



Release Notes – Zebra Android 11

11-16-05.00-RG-U00-STD-HEL-04 Release (GMS)

Highlights

This Android 11 GMS release 11-16-05.00-RG-U00-STD-HEL-04 covers MC3300ax, MC20, RZ-H271, TC52AX, CC600, CC6000, EC30, EC50, EC55, ET51, ET56, L10A, MC2200, MC2700, MC33x, MC33xR, MC9300, PS20, TC21, TC26, TC26 HC, TC52, TC52 HC, TC52x, TC52x HC, TC57, TC57x, TC72, TC77, TC8300, VC8300 & WT6300 family of products.

Please see, device compatibility under Addendum Section for more details.

Software Packages

Package Name	Description
HE_FULL_UPDATE_11-16-05.00-RG-U00-STD-HEL-04	Full package update
HE_DELTA_UPDATE_11-13-13.00-RG-U00-STD_TO_11-16-05.00-RG-U00-STD.zip	Delta package from previous release 11-13-13.00-RG-U00-STD
HE_DELTA_UPDATE_11-13-13.00-RG-U12-STD_TO_11-16-05.00-RG-U00-STD.zip	Delta package from previous release 11-13-13.00-RG-U12-STD
HE_DELTA_UPDATE_11-13-13.00-RG-U26-STD_TO_11-16-05.00-RG-U00-STD.zip	Delta package from previous release 11-13-13.00-RG-U26-STD
HE_DELTA_UPDATE_11-15-21.00-RG-U00-STD_TO_11-16-05.00-RG-U00-STD.zip	Delta package from previous release 11-15-21.00-RG-U00-STD
Releasekey_Android11_EnterpriseReset_V1.zip	Reset Package to Erase User Data Partition Only
Relasekey_Android11_FactoryReset_V1.zip	Reset Package to Erase User Data and Enterprise Partitions

Security Updates

This build is Compliant up to [Android Security Bulletin](#) of September 05, 2021.

Version Information

Below Table contains important information on versions

Description	Version
Product Build Number	11-16-05.00-RG-U00-STD-HEL-04
Android Version	11
Security Patch level	September 5, 2021
Component Versions	Please see Component Versions under Addendum section



Device Support

The products supported in this release are MC3300ax, MC20, RZ-H271, TC52AX, CC600, CC6000, EC30, EC50, EC55, ET51, ET56, L10A, MC2200, MC2700, MC33x, MC33xR, MC9300, PS20, TC21, TC26, TC26 HC, TC52, TC52 HC, TC52x, TC52x HC, TC57, TC57x, TC72, TC77, TC8300, VC8300 & WT6300 family of products.

Please see device compatibility details under Addendum Section.

New Features

- Added support for new UI design for Zebra Volume Control & Key Remapping
- Added support for Wi-Fi MAC randomization in connected state. It is enabled in out of box condition and can be disabled using EMM.
- Added support to display status of symbol security in settings.
- Added support to block the app install/update/un-install notifications during silent installation.
- Added support for streaming of Delta OTA packages (LifeGuard updates).
- Added support for OTA Delta packages available on Zebra.com will be sequential in nature.
- Added support to release every LifeGuard update as a FULL & DELTA OTA package on zebra.com.
- Added support to reduce the size of DELTA OTA package compared to previous dessert.
- Added support to reduce device downtime during LifeGuard update.
- Added support for NG Simulscan Support for camera
- Added support for RParams template for Doc Capture
- Added support for secondary BLE License for EC50, EC55
- Added support for dark display theme OOB for EC50 devices.
- Added support for updated default wallpaper OOB for EC50 devices.
- Added support for updated launcher icon outline shape to look rounded OOB for EC50, EC55, TC72, TC77, TC52x, TC57x, TC21, TC26, TC52, TC57 devices.
- Added support for setting default tone as "Lalande.ogg" for notification sound played at boot up or low battery for EC50, EC55, TC21, TC26 devices.
- Added support for enabling bordered keys in Gboard setting OOB for EC50, EC55, TC52, TC57, TC72, TC77, TC52x, TC57x, TC21, TC26 devices.
- Added support for improving Camera autofocus speed and accuracy for TC52x, EC50, EC55, TC52 and TC72.
- Added support for improving Camera autoexposure for TC52x, EC50, EC55, TC52 and TC72.
- Added support for improving image sharpness in various lighting conditions for TC52x, EC50, EC55, TC52 and TC72.
- Added support for improving Camera AWB for TC52x, EC50, EC55, TC52 and TC72.
- Added support for removing auto focus ring in Camera UI, which can be enabled by the user if desired.
- Added support for new Qorvo FEM.
- Added support for Advanced range auto focus imager for TC52AX
- Added support for BLE Channel Mask feature
- Added support for BLE Firmware recovery mechanism and beacon on battery reinsert
- Added support for SE5500 scan engine integration and MVP release
- Added support for DS9308 USB Scanner support
- Added support for enabling 5GHz Wi-Fi UNII-3 band channels for EU countries in TC52X, EC50 and TC21
- Added support to disable adaptive brightness & modified display brightness OOB for EC50/EC55 devices.

- Added support to disable Haptic feedback for EC50/EC55, MC9300, TC21, TC26, WT6300, TC52ax, TC52, TC57, TC72, TC77, C6xx, MC2200, MC2700 devices.
- Added support for Home Screen layout customization for all zebra specific application & tools for EC50, EC55
- Added support for VoWiFi for Orange.
- Added support for Vodafone UK.
- Added support for Erillisverkot Public Safety MVNO.
- Added support for APN details for Spark NZ operator.
- Added support for Zebra workstation connect solution on TC52ax & ET56

Resolved Issues

- Fixed: 39795 MC93 Dotcode barcodes missing timestamp
- Fixed: 41890 Roam Stickiness & Signal Reporting concern.
- Fixed: 40408 WWAN disconnecting at high temperatures
- Fixed: 41635 TC57/TC77/TC26 Cherry pick the changes to SDM660 Android Oreo release
- Fixed: 40382 StageNow Error with Creating DSDS setting in CellularMgr
- Fixed: 39868 MC9300: Remap Diamond Key - 3x3 layout to include question mark (?)
- Fixed: 39918 TC52 TC57 Disable MMI code which reveals PhoneInfo Screen
- Fixed: 41910 Resolved an issue wherein first touch was not working correctly after resume
- Fixed: 43358 Resolved an issue wherein first created profile after deleting the default profile, does not connect automatically
- Fixed: 40859 LTE data drops observed with custom APN using Firstnet SIM
- Fixed: 43012 Stagenow "CONFIGURE ZERO TOUCH NETWORK".BIN file process fails on VMTs SDM660
- Fixed: 41294 ET51 Integrated Scanner Customer reporting ET51 display \ touch becoming sluggish in the cold
- Fixed: 39982 'VerifyApps' API returns False.
- Fixed: 40212 TC77 01-23-18.00-OG-U09-H14 Time in Webview issue, sometimes the Clock CSP causes the time not to display correctly
- Fixed: 40468 VC8300 dropping barcode characters after BSP upgrade (1.30.04, LG update 08) using DS3678 w/cradle
- Fixed: 41882 Resolved an issue wherein it was not possible to provision the device using QR code with EXTRA_PROVISIONING_WIFI_PROXY_HOST and EXTRA_PROVISIONING_WIFI_PROXY_PORT details
- Fixed: 43802 OS Update fails sometimes
- Fixed: 40440 Disable MMI code which reveals PhoneInfo Screen
- Fixed: 43738 Updating movistar and telenor apn
- Fixed: 43683 Resolved an issue wherein USB to Serial Port converter was not working on a 3rd party cradle
- Fixed: 41003 ET51 BlueParrot XT 250/350, HS3100 Distant Noise Pickup / Gain Levels Differ, Compared to TC52/WT60
- Fixed: 43314 PS20 not able to use scanner after update to 02-11-01.00 LG06
- Fixed: 38958 Atlas Devices Not Using Domain Name Sent for VPN Connection
- Fixed: 41038 Updated APN configuration for Telenor carrier
- Fixed: 37883 PAC file with toLowerCase/toUpperCase are failing to parse
- Fixed: 40284 Unable to use proxy
- Fixed: 40400 WAN disconnects at high temperatures
- Fixed: 40078 EC30 BLE advertisement power not achieving MAX values
- Fixed: 40075 VC80x unexpectedly rebooting
- Fixed: 39808 MC33 Dotcode barcodes missing timestamp
- Fixed: 41622 Update WT6300 Touch Panel firmware to v40

Fixed: 40388 VC80x ignition shutoff countdown does not reset when ignition turned back on
Fixed: 39697 TC51 press and hold effect was removed after 30secs
Fixed: 43818 Wrong Korean translation in Wi-Fi advanced option
Fixed: 43383 Stagenow does not process scanned barcode after OEMConfig installed
Fixed: 41725 Suspend and Resume APIs intermittently fails
Fixed: 41450 Stagenow 5.0.1.0 and Mxv10.2 IntentManager does not show input field for Json String]

Fixed: 41260 On Android10 pulse application is not working
Fixed: 40655 On selecting DataWedge as a keyboard from the device virtual keyboard settings and disabling Google GBoard, it does not display scanned data
Fixed: 40212 On TC77, sometimes the Clock CSP causes the time not to display correctly
Fixed: 44335/44185 NFC reader - Null read when scanning Imprivata badge after device sleep
Fixed: 43940 DNS alias could not be resolved
Fixed: 44265 Android poor battery life
Fixed: 43907 NTP update interval not working
Fixed: 43148 OEMConfig giving error message when WLAN channels are specified as hyphenated range
Fixed: 41757 TC52 and TC57s get into a state where they will not scan from the Start Menu, StageNow or Datawedge Demo
Fixed: 41255 TC26 Stuck at recovery mode during EMM enrollmenmt
Fixed: 41247 TC57 Oreo Scanner sporadically not working
Fixed: 40859 LTE data drops observed with custom APN using Firstnet SIM
Fixed: 40301 Webview does not load after Ent. Reset with GMS Restricted persistent profile
Fixed: 40534 PS20 SE4710 firmware update improvement.
Fixed: 40449 Camera application crashed after few time in use
Fixed: 40239 EMC devices without camera fail to enroll into Microsoft Intune from welcome screen
Fixed: 38723 QXDM logs exceeding the max configured log size -Device running out of memory
Fixed: 44151 ET51/56 - Glove Touch mode Issue
Fixed: 44486 ET51/56 – Camera Image Upside down
Fixed: 44265 BT module shows incorrect battery usage in bugreport
Fixed: 44031 TC77 Is experiencing Ghost Like touches on the screen even though no physical contact is made on the device's touch Screen.
Fixed: 44260 PTT Call cannot be initiated
Fixed: 44047 EMDK Barcode App crashed after upgraded to TC56 Nougat
Fixed: 43017 Notify User about power supply DC/DC module failure using red blinking LED

Usage Notes

- None

Known Constraints

- In-order to avoid any inconsistencies in Settings UI it is recommended to wait for a few seconds after the device boots up before launching settings UI.
- On upgrading a device from A8/A9/A10 to A11, NFC manager configuration need to be re-applied.
- Starting Android 11 on SDM660, an UPL file cannot consist of both Full OTA and Delta OTA package. On A11 customer can directly install the Full OTA package of required LG image
- One second Bluetooth jitter noticed in 2.4GHz band.

- Ethernet UI is accessible from settings despite being disabled
- RxLogger fails to store logs in internal storage when external SDCard is formatted as internal/adaptable, or it is ejected during run time.
- BLE FW update will not work without enabling location service under settings.



Important Links

- [Installation and setup instructions](#) (if the link does not work, please copy it to browser and try)
- [Zebra Techdocs](#)
- [Developer Portal](#)

Addendum

Device Compatibility

This software release has been approved for use on the following devices.

Device Family	Part Number		Device Specific Manuals and Guides
MC3300ax	MC330X-SJ2EG4NA MC330X-SJ3EG4NA MC330X-SJ4EG4NA MC330X-SJ2EG4RW MC330X-SJ3EG4RW MC330X-SJ4EG4RW MC330X-SA2EG4NA MC330X-SA3EG4NA MC330X-SA4EG4NA MC330X-SA2EG4RW MC330X-SA3EG4RW MC330X-SA4EG4RW MC330X-SA3EG4IN MC330X-SA4EG4IN MC330X-SJ3EG4IN MC330X-SJ4EG4IN MC330X-SJ2EG4RU MC330X-SJ3EG4RU MC330X-SA2EG4RU MC330X-SA3EG4RU MC330X-SA3EG4TR MC330X-SA4EG4TR MC330X-SE2EG4NA MC330X-SE3EG4NA MC330X-SE4EG4NA MC330X-SE2EG4RW MC330X-SE3EG4RW MC330X-SE4EG4RW MC330X-SG2EG4NA MC330X-SG3EG4NA MC330X-SG4EG4NA MC330X-SG2EG4RW MC330X-SG3EG4RW MC330X-SG4EG4RW	MC330X-GJ2EG4NA MC330X-GJ3EG4NA MC330X-GJ4EG4NA MC330X-GJ2EG4RW MC330X-GJ3EG4RW MC330X-GJ4EG4RW MC330X-GJ3EG4IN MC330X-GJ4EG4IN MC330X-GJ2EG4RU MC330X-GJ3EG4RU MC330X-GJ4EG4RU MC330X-GE2EG4NA MC330X-GE3EG4NA MC330X-GE4EG4NA MC330X-GE2EG4RW MC330X-GE3EG4RW MC330X-GE4EG4RW MC330X-GE2EG4RU MC330X-GE3EG4RU MC330X-GE4EG4RU MC330X-GE3EG4IN MC330X-GE4EG4IN MC330X-GJ3EG4RW01 MC330X-GJ3EG4NA01 MC330X-GJ3EG4IN01 MC330X-GJ3BG4IN01 MC330X-GJ3BG4RW01 MC330X-GJ3BG4NA01 MC330X-SJ3BG4RW MC330X-GE4BG4RW MC330X-GE3BG4RW MC330X-GJ3BG4RW MC330X-GJ4BG4RW MC330X-SJ4BG4NA	MC3300ax Home Page

	MC330X-SG3EG4IN MC330X-SE3EG4RU MC330X-SG3EG4RU MC330X-SG3EG4TR MC330X-SG4EG4TR	MC330X-GE2BG4RW MC330X-GE4BG4NA MC330X-GJ4BG4NA MC330X-GJ2BG4RW MC330X-GE3BG4NA	
MC20	RZ-H271	MC200A-GA2S40JP	MC20 Home Page
TC52AX	TC520L-1YFMU7P-NA TC520L-1YFMU7T-NA TC520L-1YLMU7T-NA	TC520L-1YFMU7P-A6 TC520L-1YFMU7T-A6 TC520L-1YLMU7T-A6	TC52ax Home Page
CC600	CC600-5-3200LNNA CC600-5-3200LNWW	CC600-5-3200LNRU CC600-5-3200LNIN	CC600 Home Page
CC6000	CC6000-10-3200LCWW CC6000-10-3200PCWW CC6000-10-3200LCNA CC6000-10-3200NLCNA	CC6000-10-3200LCRU CC6000-10-3200PCNA CC6000-10-3200LNNA CC6000-10-3200NLCWW	CC6000 Home Page
EC30	EC300K-1SA2ANA EC300K-1SA2AA6 EC300K-1SA2AIA	KT-EC300K-1SA2BNA-10 KT-EC300K-1SA2BA6-10	EC30 Home Page
EC50	EC500K-01B132-NA EC500K-01B242-NA EC500K-01B243-NA EC500K-01D141-NA EC500K-01B112-NA EC500K-01B222-NA EC500K-01B223-NA EC500K-01D121-NA	EC500K-01B243-A6 EC500K-01D141-A6 EC500K-01B132-A6 EC500K-01B242-A6 EC500K-01B112-A6 EC500K-01B222-A6 EC500K-01B223-A6 EC500K-01D121-A6	EC50 Home Page
EC55	EC55AK-01B112-NA EC55AK-11B112-NA EC55AK-11B132-NA EC55AK-21B222-NA EC55AK-21B223-NA EC55AK-21B242-NA EC55AK-21B243-NA EC55AK-21D121-NA EC55AK-21D141-NA EC55AK-21D221-NA EC55BK-01B112-A6 EC55BK-11B112-A6 EC55BK-11B112-BR EC55BK-11B112-IA EC55BK-11B112-ID EC55BK-11B112-RU EC55BK-11B112-XP EC55BK-11B132-A6	EC55BK-11B223-A6 EC55BK-21B222-A6 EC55BK-21B223-A6 EC55BK-21B223-BR EC55BK-21B223-IA EC55BK-21B223-ID EC55BK-21B223-RU EC55BK-21B223-XP EC55BK-21B242-A6 EC55BK-21B243-A6 EC55BK-21D121-A6 EC55BK-21D121-BR EC55BK-21D121-IA EC55BK-21D121-ID EC55BK-21D121-RU EC55BK-21D121-XP EC55BK-21D141-A6	EC55 Home Page
ET51	ET51CT-G21E-00A6 ET51CT-G21E-00NA	ET51CE-G21E-00IA ET51CE-G21E-SFA6	ET51 Home Page

	ET51CE-G21E-00NA ET51CE-G21E-00A6	ET51CE-G21E-SFNA	
ET56	ET56DT-G21E-00NA ET56ET-G21E-00A6 ET56ET-G21E-00IA	ET56DE-G21E-00A6 ET56DE-G21E-00NA	ET56 Home Page
L10A	RTL10B1-xxxxxxxxNA (North America) RTL10B1-xxAxxX0x00A6 (ROW) Note: 'x' Stands for wild card for different configurations	RTL10B1-xxAxxX0x00IN (India) RTL10B1-xxxxxxxxRU (Russia)	L10A Home Page
MC2200	MC220K-2A3S3RW MC220K-2A3E3NA01 MC220K-2A3E3IN01 MC220K-2A3E3RW01 MC220K-2B3E3RW MC220K-2B3S3RW MC220K-2B3S3NA MC220K-2B3S3IN MC220K-2B3S3RU MC220K-2B3S3TR	MC220K-2B3S3XP MC220K-2A3S3RU MC220J-2A3S2RW MC220J-2A3S2NA MC220J-2A3S2IN MC220J-2A3S2XP MC220J-2A3S2RU MC220J-2A3E2RU MC220J-2A3S2TR	MC2200 Home Page
MC2700	MC27AK-2B3S3NA MC27AK-4B3S3NA MC27BJ-2A3S2ID MC27BJ-2A3S2IN MC27BJ-2A3S2RW MC27BJ-2A3S2XP MC27BK-2B3S3ID MC27BK-2B3S3IN	MC27BK-2B3S3RW MC27BK-2B3S3XP MC27BK-4B3S3RW MC27BJ-2A3S2RU MC27BJ-2A3S2TR MC27BK-2B3S3RU MC27BK-2B3S3TR MC27AJ-2A3S2NA	MC2700 Home Page
MC3300x	MC330L-GE2EG4NA MC330L-GE2EG4RU MC330L-GE2EG4RW MC330L-GE3EG4IN MC330L-GE3EG4NA MC330L-GE3EG4RU MC330L-GE3EG4RW MC330L-GE4EG4IN MC330L-GE4EG4NA MC330L-GE4EG4RU MC330L-GE4EG4RW MC330L-GJ2EG4NA MC330L-GJ2EG4RU MC330L-GJ2EG4RW MC330L-GJ3EG4IN MC330L-GJ3EG4NA MC330L-GJ3EG4RU MC330L-GJ3EG4RW MC330L-GJ4EG4IN	MC330L-SC2EG4NA MC330L-SC2EG4RW MC330L-SC3EG4NA MC330L-SC3EG4RW MC330L-SC4EG4NA MC330L-SC4EG4RW MC330L-SE2EG4NA MC330L-SE2EG4RW MC330L-SE3EG4NA MC330L-SE3EG4RU MC330L-SE3EG4RW MC330L-SE4EG4NA MC330L-SE4EG4RW MC330L-SG2EG4NA MC330L-SG2EG4RW MC330L-SG3EG4IN MC330L-SG3EG4NA MC330L-SG3EG4RU MC330L-SG3EG4RW	MC3300x Home Page

	<p>MC330L-GJ4EG4NA MC330L-GJ4EG4RU MC330L-GJ4EG4RW MC330L-GL2EG4NA MC330L-GL2EG4RW MC330L-GL3EG4IN MC330L-GL3EG4NA MC330L-GL3EG4RW MC330L-GL4EG4IN MC330L-GL4EG4NA MC330L-GL4EG4RW MC330L-RC2EG4NA MC330L-RC2EG4RW MC330L-RC3EG4NA MC330L-RC3EG4RW MC330L-RC4EG4NA MC330L-RC4EG4RW MC330L-RL2EG4NA MC330L-RL2EG4RW MC330L-RL3EG4NA MC330L-RL3EG4RW MC330L-RL4EG4NA MC330L-RL4EG4RW MC330L-SA2EG4NA MC330L-SA2EG4RU MC330L-SA2EG4RW MC330L-SA3EG4IN MC330L-SA3EG4NA MC330L-SA3EG4RU MC330L-SA3EG4RW MC330L-SA3EG4TR MC330L-SA4EG4IN MC330L-SA4EG4NA MC330L-SA4EG4RW MC330L-SA4EG4TR</p>	<p>MC330L-SG3EG4TR MC330L-SG4EG4NA MC330L-SG4EG4RW MC330L-SG4EG4TR MC330L-SJ2EG4NA MC330L-SJ2EG4RU MC330L-SJ2EG4RW MC330L-SJ3EG4IN MC330L-SJ3EG4NA MC330L-SJ3EG4RU MC330L-SJ3EG4RW MC330L-SJ4EG4IN MC330L-SJ4EG4NA MC330L-SJ4EG4RW MC330L-SK2EG4NA MC330L-SK2EG4RW MC330L-SK3EG4NA MC330L-SK3EG4RU MC330L-SK3EG4RW MC330L-SK4EG4NA MC330L-SK4EG4RW MC330L-SL2EG4NA MC330L-SL2EG4RW MC330L-SL3EG4NA MC330L-SL3EG4RW MC330L-SL4EG4NA MC330L-SL4EG4RW MC330L-SM2EG4NA MC330L-SM2EG4RU MC330L-SM2EG4RW MC330L-SM3EG4NA MC330L-SM3EG4RW MC330L-SM4EG4NA MC330L-SM4EG4RW</p>	
<p>MC3300xR</p>	<p>MC333U-GJ2EG4EU MC333U-GJ2EG4IL MC333U-GJ2EG4JP MC333U-GJ2EG4RU MC333U-GJ2EG4US MC333U-GJ3EG4EU MC333U-GJ3EG4RU MC333U-GJ3EG4US MC333U-GJ4EG4EU MC333U-GJ4EG4IN MC333U-GJ4EG4JP MC333U-GJ4EG4RU MC333U-GJ4EG4SL MC333U-GJ4EG4TH MC333U-GJ4EG4US MC333U-GJ4EG4WR MC339U-GE2EG4EU MC339U-GE2EG4JP</p>	<p>MC339U-GE3EG4RU MC339U-GE3EG4US MC339U-GE4EG4EU MC339U-GE4EG4IN MC339U-GE4EG4JP MC339U-GE4EG4RU MC339U-GE4EG4TH MC339U-GE4EG4US MC339U-GE4EG4WR MC339U-GF2EG4EU MC339U-GF2EG4RU MC339U-GF2EG4US MC339U-GF3EG4EU MC339U-GF3EG4RU MC339U-GF3EG4TH MC339U-GF3EG4US MC339U-GF4EG4EU MC339U-GF4EG4RU</p>	<p>MC3300xR Home Page</p>

	MC339U-GE2EG4RU MC339U-GE2EG4US MC339U-GE2EG4WR MC339U-GE3EG4EU	MC339U-GF4EG4SL MC339U-GF4EG4TH MC339U-GF4EG4US MC339U-GF4EG4WR	
MC93	MC930B-GSXXG4XX MC930P-GSXXG4XX MC930P-GFXXG4XX Note: 'x' Stands for wild card for different configurations	MC930B-GSXXG4NA-XX MC930P-GSXXG4NA-XX	MC9300 Home Page
PS20	PS20J-P4G1A600 PS20J- P4G1A600-10 PS20J- B2G1A600 PS20J- B2G1A600-10 PS20J- P4H1A600 PS20J- P4H1A600-10 PS20J- B2G2CN00 PS20J- P4H2CN00	PS20J-P4G2CN00 PS20J- P4G1NA00 PS20J- P4G1NA00-10 PS20J- B2G1NA00 PS20J- B2G1NA00-10 PS20J- P4H1NA00 PS20J- P4H1NA00-10 PS20J- P4G1RU00	PS20 Home Page
TC21	TC210K-01A222-A6 TC210K-01A242-A6 TC210K-01D221-A6 TC210K-01D241-A6 TC210K-01B212-A6 TC210K-01B232-A6 TC210K-01A422-A6 TC210K-01A442-A6 TC210K-0HD224-A6 TC210K-0HB224-A6 TC210K-0HB222-A6 TC210K-01A423-A6 TC210K-0JB224-A6 TC210K-01B422-NA TC210K-01A222-NA TC210K-01D221-NA TC210K-01D241-NA TC210K-0JD224-NA TC210K-0JB224-NA TC210K-01A242-NA TC210K-01A442-NA TC210K-01B212-NA TC210K-01B232-NA	TC210K-01A423-NA TC210K-0HD224-NA TC210K-0HB224-NA TC210K-0HB222-NA TC210K-01A422-NA TC210K-0HB224-IA TC210K-01A222-IA TC210K-01A242-IA TC210K-01A442-IA TC210K-01A422-IA TC210K-01B212-IA TC210K-01B232-IA TC210K-01A423-IA TC210K-01B232-TR TC210K-01B212-TR TC210K-01D221-TR TC210K-01D241-TR TC210K-01B212-RU TC210K-01B232-RU TC210K-01A222-RU TC210K-0HD224-FT TC210K-01B212-XP	TC21 Home Page
TC21 HC	TC210K-0HD224-NA KT-TC210K-0HD224-FT TC210K-0HD224-A6 TC210K-0HB224-A6 TC210K-0JB224-A6 TC210K-0JD224-NA TC210K-0JB224-NA TC210K-0HB224-NA TC210K-0HB222-NA TC210K-0HB224-IA	KT-TC210K-0HB224- PTTP1-A6 KT-TC210K-0HB224- PTTP2-A6 KT-TC210K-0HD224-WFC1- NA KT-TC210K-0HD224-WFC2- NA KT-TC210K-0HD224-WFC1- FT	TC21 Home Page

	<p>TC210K-0HB222-NA KT-TC210K-0HD224-PTTP1-NA KT-TC210K-0HD224-PTTP2-NA KT-TC210K-0HD224-PTTP1-FT KT-TC210K-0HD224-PTTP2-FT KT-TC210K-0HD224-PTTP1-A6 KT-TC210K-0HD224-PTTP2-A6</p>	<p>KT-TC210K-0HD224-WFC2-FT KT-TC210K-0HD224-WFC1-A6 KT-TC210K-0HD224-WFC2-A6 KT-TC210K-0HB224-WFC1-A6 KT-TC210K-0HB224-WFC2-A6</p>	
TC26	<p>TC26BK-11A222-A6 TC26BK-11A242-A6 TC26BK-11A422-A6 TC26BK-11A423-A6 TC26BK-11A442-A6 TC26BK-11B212-A6 TC26BK-11B232-A6 TC26BK-11B412-A6 TC26BK-11D221-A6 TC26BK-11D241-A6 TC26BK-11D421-A6 TC26BK-21D221-A6 TC26BK-21A222-A6 TC26BK-1HB224-A6 TC26BK-1HD224-A6 TC26BK-1JB224-A6 TC26BK-21A442-A6 TC26AK-11A222-NA TC26AK-11A242-NA TC26AK-11A422-NA TC26AK-11A423-NA TC26AK-11B212-NA TC26AK-11B232-NA TC26AK-11D221-NA TC26AK-11D241-NA TC26AK-1HB222-NA TC26AK-1HB224-NA TC26AK-1HD224-NA TC26AK-1JD224-NA TC26AK-21A222-NA TC26AK-1JB224-NA</p>	<p>TC26AK-11A442-NA TC26BK-11A222-IA TC26BK-11A242-IA TC26BK-11A442-IA TC26BK-11B212-IA TC26BK-11B232-IA TC26BK-21A222-IA TC26BK-1HB224-IA TC26BK-11D221-IA TC26BK-11A222-BR TC26BK-11A242-BR TC26BK-11A422-BR TC26BK-11A423-BR TC26BK-11A442-BR TC26BK-11B212-BR TC26BK-11B232-BR TC26BK-11D221-BR TC26BK-11D241-BR TC26BK-1HB224-BR TC26DK-11B212-TR TC26DK-11B232-TR TC26BK-11B212-TR TC26BK-11B232-TR TC26BK-11B212-RU TC26BK-11A222-RU TC26BK-11B232-RU TC26BK-11A422-RU TC26BK-11B212-ID TC26BK-11A222-ID TC26BK-11B212-XP TC26AK-1HD224-FT</p>	<p>TC26 Home Page</p>
TC26 HC	<p>TC26BK-1HD224-A6 TC26BK-1HB224-A6 TC26BK-1HB224-BR TC26AK-1HD222-NA TC26BK-1HB224-IA TC26AK-1JB224-NA TC26BK-1JB224-A6 TC26AK-1HD224-NA</p>	<p>KT-TC26AK-1HD224-PTTP2-NA KT-TC26AK-1HD224-PTTP1-FT KT-TC26AK-1HD224-PTTP2-FT KT-TC26AK-1HD224-WFC1-NA</p>	<p>TC26 Home Page</p>

	TC26AK-1HB224-NA KT-TC26AK-1HD224-FT TC26AK-1HB222-NA TC26AK-1JD224-NA KT-TC26BK-1HD224-PTTP1-A6 KT-TC26BK-1HD224-PTTP2-A6 KT-TC26BK-1HB224-PTTP1-A6 KT-TC26BK-1HB224-PTTP2-A6 KT-TC26AK-1HD224-PTTP1-NA	KT-TC26AK-1HD224-WFC2-NA KT-TC26AK-1HD224-WFC1-FT KT-TC26AK-1HD224-WFC2-FT KT-TC26BK-1HD224-WFC1-A6 KT-TC26BK-1HD224-WFC2-A6 KT-TC26BK-1HB224-WFC1-A6 KT-TC26BK-1HB224-WFC2-A6	
TC52	TC520K-1PEZU4P-A6 TC520K-1PEZU4P-NA	TC520K-1PEZU4P-IA TC520K-1PEZU4P-FT	TC52 Home Page
TC52 – AR1337 Camera	TC520K-1PFZU4P-A6	TC520K-1PFZU4P-NA	TC52 Home Page
TC52 HC	TC520K-1HEZU4P-NA TC520K-1HEZU4P-EA TC520K-1HEZU4P-A6 TC520K-1HEZU4P-FT TC520K-1HEZU4P-IA KT-TC520K-1HCMH6P-PTT1-NA KT-TC520K-1HCMH6P-PTT2-NA KT-TC520K-1HCMH6P-PTT1-FT KT-TC520K-1HCMH6P-PTT2-FT KT-TC520K-1HCMH6P-PTT1-A6 KT-TC520K-1HCMH6P-PTT2-A6 KT-TC520K-1HEZU4P-PTT1-NA KT-TC520K-1HEZU4P-PTT2-NA	KT-TC520K-1HEZU4P-PTT1-FT KT-TC520K-1HEZU4P-PTT2-FT KT-TC520K-1HEZU4P-PTT1-A6 KT-TC520K-1HEZU4P-PTT2-A6 KT-TC520K-1HEZU4P-WFC1-NA KT-TC520K-1HEZU4P-WFC2-NA KT-TC520K-1HEZU4P-WFC1-FT KT-TC520K-1HEZU4P-WFC2-FT KT-TC520K-1HEZU4P-WFC1-A6 KT-TC520K-1HEZU4P-WFC2-A6 KT-TC52-1HEZWFC1-NA	TC52 HC Home Page
TC52x	TC520K-1XFMU6P-NA TC520K-1XFMU6P-A6 TC520K-1XFMU6P-TK	TC520K-1XFMU6P-FT TC520K-1XFMU6P-IA	TC52x Home Page
TC52x HC	TC520K-1HCMH6P-NA TC520K-1HCMH6P-FT TC520K-1HCMH6P-A6 TC520K-1HCMH6P-PTTP1-NA	TC520K-1HCMH6P-PTTP2-A6 TC520K-1HCMH6P-WFC1-NA TC520K-1HCMH6P-WFC2-NA	TC52x Home Page

	TC520K-1HCMH6P-P TTP2-NA TC520K-1HCMH6P-P TTP1-FT TC520K-1HCMH6P-P TTP2-FT TC520K-1HCMH6P-P TTP1-A6	TC520K-1HCMH6P-WFC1-FT TC520K-1HCMH6P-WFC2-FT TC520K-1HCMH6P-WFC1-A6 TC520K-1HCMH6P-WFC2-A6 KT-TC52X-1HCMWFC1-NA	
TC57	TC57HO-1PEZU4P-A6 TC57HO-1PEZU4P-IA TC57HO-1PEZU4P-NA TC57HO-1PEZU4P-XP	TC57HO-1PEZU4P-BR TC57HO-1PEZU4P-ID TC57HO-1PEZU4P-FT	TC57 Home Page
TC57 – AR1337 Camera	TC57HO-1PFZU4P-A6	TC57HO-1PFZU4P-NA	TC57 Home Page
TC57x	TC57HO-1XFMU6P-A6 TC57HO-1XFMU6P-BR TC57HO-1XFMU6P-IA TC57HO-1XFMU6P-FT	TC57HO-1XFMU6P-ID TC57JO-1XFMU6P-TK TC57HO-1XFMU6P-NA TC57HO-1XFMU6P-RU	TC57X Home Page
TC72	TC720L-0ME24B0-A6 TC720L-0ME24B0-NA TC720L-0ME24B0-BR TC720L-0ME24B0-IA	TC720L-0ME24B0-TN TC720L-0ME24B0-FT TC720L-0MJ24B0-A6 TC720L-0MJ24B0-NA	TC72 Home Page
TC72 – AR1337 Camera	TC720L-0MK24B0-A6 TC720L-0MK24B0-NA	TC720L-0ML24B0-A6 TC720L-0ML24B0-NA	TC72 Home Page
TC77	TC77HL-5ME24BG-A6 TC77HL-5ME24BD-IA TC77HL-5ME24BG-FT (FIPS_SKU) TC77HL-7MJ24BG-A6 TC77HL-5ME24BD-ID TC77HL-5ME24BG-EA TC77HL-5ME24BG-NA	TC77HL-5MG24BG-EA TC77HL-6ME34BG-A6 TC77HL-5ME24BD-BR TC77HL-5MJ24BG-A6 TC77HL-5ME24BG-RU TC77HL-5MJ24BG-NA TC77HL-7MJ24BG-NA	TC77 Home Page
TC77 – AR1337 Camera	TC77HL-5MK24BG-A6 TC77HL-5MK24BG-NA	TC77HL-5ML24BG-A6 TC77HL-5ML24BG-NA	TC77 Home Page
TC8300	TC83B0-x005A510NA TC83B0-x005A61CNA TC83BH-x205A710NA TC83B0-x005A510RW TC83B0-x005A61CRW TC83BH-x205A710RW TC83B0-x005A510IN TC83B0-x005A61CIN	TC83BH-x206A710RW TC83B0-4005A610NA TC83B0-4005A610RW TC83B0-4005A610IN TC83B0-5005A610NA TC83B0-5005A610RW TC83B0-5005A610IN	TC8300 Home Page

	TC83BH-x205A710IN TC83BH-x206A710NA Note: 'x' Stands for wild card for different configurations	TC83B0-x005A510TA TC83BH-x205A710TA	
VC8300 8"	VC83-08FOCABAABA-I VC83-08FOCQBAABA-I VC83-08FOCQBAABANA VC83-08SOCABAABA-I	VC83-08SOCQBAABA-I VC83-08SOCQBAABANA VC83-08SOCQBAABAIN	VC8300 Home Page
VC8300 10"	VC83-10SSCNBAABANA VC83-10SSCNBAABA-I	VC83-10SSCNBAABARU VC83-10SSCNBAABATR	
WT6300	WT63B0-TS0QNERW WT63B0-TS0QNENA WT63B0-TS0QNE01 WT63B0-TX0QNERW WT63B0-TX0QNENA WT63B0-TS0QNETR	WT63B0-TS0QNERU WT63B0-TX0QNERU WT63B0-KS0QNERW WT63B0-KS0QNENA WT63B0-KX0QNERW WT63B0-KX0QNENA	WT6300 Home Page

Component Versions

Component / Description	Version
Acoustics Profiles	MC3300ax: General: FR1.1, FR2.1, FR3.1 Cellular: NA MC20: General: XR1.3 Cellular: NA RZ-H271: General: XR2.4 Cellular: NA TC52AX: General: YR1.2, YR3.1 Cellular: NA CC600: General: MR2.1 Cellular: NA CC6000: General: MR1.1, MR3.1, MR4.1 Cellular: NA EC30: General: LR1.2 Cellular: NA EC50: General: UR1.2 Cellular: NA EC55: General: UR2.2 Cellular: NA ET51: General: PR1.2, PR3.2 Cellular: NA ET56: General: PR2.2, PR4.1 Cellular: NA L10A: General: OR1.1Reva, OR1.1RevB, OR2.1RevA, OR2.1RevB Cellular: NA MC2200: General: VR1.2 Cellular: NA MC2700: General: VR2.2 Cellular: NA MC33x: General: DR3.2, DR1.2, DR2.2 Cellular: NA MC33xR: General: RR1.2, RR2.2 Cellular: NA MC93: General: KR1.2, KR2.2, KR3.2, KR4.2 Cellular: NA PS20: General: JR1.1, JR2.2 Cellular: NA TC21: General: SR1.2, SR5.2 Cellular: NA TC26: General: SR2.2, SR6.2, SR9.3 Cellular: SR2.2 TC21 HC: General: SR3.2, SR7.2 Cellular: NA TC26 HC: General: SR4.2, SR8.2 Cellular: SR4.2 TC52: General: GR1.4 Cellular: NA TC52 HC: General: GR2.4 Cellular: NA TC52x: General: TR1.3

	Cellular: NA TC52x HC: General: TR3.3 Cellular: NA TC57: General: GR3.4 Cellular: GR3.1 TC57x: General: TR2.3 Cellular: TR2.1 TC72: General: HR1.3 Cellular: NA TC77: General: HR2.3 Cellular: HR2.1 TC8300: General: NR1.2, NR2.2, NR3.2, NR4.2 Cellular: NA VC8300: General: QR1.1, QR2.1 Cellular: NA WT6300: General: WR1.2 Cellular: NA
Linux Kernel	4.19.157-perf
AnalyticsMgr	10.0.0.1002
Android SDK Level	30
Audio (Microphone and Speaker)	0.30.0.0
Battery Manager	1.2.9
Bluetooth Pairing Utility	3.24
Camera	2.0.002
DataWedge	11.1.31
EMDK	11.0.118.4018
Files	r_aml_301501600
License Manager and License agent	6.0.8 and 6.0.23.5.0.1
MXMF	11.1.0.21
NFC	NFC_NCIHALx_AR18C0.b.1.0
OEM info	9.0.0.466
OSX	QCT. 110.11.10.9
RXlogger	7.0.1.0
ZWC	1.0.549
Scanning Framework	31.0.20.0

StageNow	5.4.0.14
Touch Panel (FW)	<p>MC3300ax: Version: 38 Mode: Finger and Stylus</p> <p>MC20: Version: 27 Mode: Finger Only</p> <p>RZ-H271: Version: 27 Mode: Finger Only</p> <p>TC52AX: Version: 0.8.1-finger-4-0:0x39c6fa Mode: Finger Only</p> <p>CC600: Version: 06 Mode: Finger only</p> <p>CC6000: Version: ilitek firmware version is 6.0.0.3.255.255.255.255 Mode: finger only</p> <p>EC30: Version:45 Mode: Finger only</p> <p>EC50: Version: 06 Mode: Finger only</p> <p>EC55: Version: 06 Mode: Finger only</p> <p>ET51: Version: 0410050000 Mode: Finger Only</p> <p>ET56: Version: 0410050000 Mode: Finger Only</p> <p>L10A: Version: 00_ver8 Mode: Finger and passive Stylus</p> <p>MC2200: Version: 10 Mode: Finger Only</p> <p>MC2700: Version: 10 Mode: Finger Only</p> <p>MC33x: Version: 38 Mode: Finger and Stylus</p> <p>MC33xR: Version: 38 Mode: Finger and Stylus</p> <p>MC93: Version: 1.1.0-Finger-2-0:0xc0ef11 Mode: Finger Only</p> <p>PS20: Version:08 Mode: Finger Only</p> <p>TC21: Version: 06 Mode: Finger only</p> <p>TC26: Version: 06 Mode: Finger only</p> <p>TC52: Version:1.8.3-Finger-2-0:0x68cffa Mode: Finger Only</p> <p>TC52x: Version: 0.8.1-Finger-4-0:0x39c6fa Mode: Finger Only</p> <p>TC57: Version:1.8.3-Finger-2-0:0x68cffa Mode: Finger Only</p> <p>TC57x: Version: 0.8.1-Finger-4-0:0x39c6fa Mode: Finger Only</p> <p>TC72: Version: 2.0.1-Finger-1-0:0x826e9a Mode: Finger Only</p> <p>TC77: Version: 2.0.1-Finger-1-0:0x826e9a</p>

	TC8300: Mode: Finger Only Version: 18 VC8300: Mode: Finger Only Version: 0.0.6-Finger-3-0 Mode: Finger only WT6300: Version:40 Mode: Finger Only
WLAN	FUSION_QA_2_1.4.0.009_R (Wi-Fi5) FUSION_SA_2_1.4.0.005_R (Wi-Fi6)
WorryFree WiFi	WFW_A_2_6.3.0.009_R
Zebra Bluetooth	11.1.6
Zebra Volume Control	3.0.0.49
Zebra Data Service	10.0.4.1030
Embedded Controller Firmware	VC8300 8"/10": 3.3.01

Revision History

Rev	Description	Date
1.0	Initial release	October 22, 2021