



TC75 OPERATING SYSTEM BSP 11.04 - HOTFIX CFE PAABVC02-001-R00 RELEASE NOTES

INTRODUCTION

SPR 28477 - Scanner Illumination doesn't come on intermittently.

DESCRIPTION

The enclosed patch 'FirmwareUpdateApp.apk' fixes the issue that scanner illumination doesn't come on intermittently.

Note: Refer to 'Readme.docx' for more information.

CONTENTS

FirmwareUpdateApp.apk

DEVICE COMPATIBILITY

This software release has been approved for use with the following Zebra devices,

Device	Operating System	OEM Version
TC75	Android KK 4.4.3	v01104 and v01404

INSTALLATION REQUIREMENTS

This SW is intended for the TC75 device running v01104 and v01404 build.

INSTALLATION INSTRUCTIONS

Refer 'Readme.docx' for installation instruction

RELEASE DATE

October 21, 2015