



MC2100 OPERATING SYSTEM FOR CORE BSP 03.34.0023 - LOCALIZED RELEASE NOTES

INTRODUCTION

From the sales floor to the backroom, the Zebra MC2100 mobile computer has what it takes to affordably automate the capture of inventory data right at the point of work. Leveraging Zebra's Mobility Platform Architecture 2.0, the MC2100 offers plenty of processing power, industry-leading data capture capabilities, rugged design, superior ergonomics, flexible data capture options, plus centralized management. Support for Zebra's RhoElements application development platform allows you to create cross-platform applications that work on different mobile computers with different operating systems. MC2100 is available in Wireless LAN (802.11b/g/n) and Batch configuration

DESCRIPTION

1. **CCX v4 certified** WLAN Fusion Software version "**FUSION_X_2.01.2.0.002R**"
2. CMI(ChiMei) Display Support is added
3. Integrated PTT Express v1.1.49
4. RhoElements Framework v02.02.01.12.00
5. RhoElements BasicBrowser v2.0 (WLAN configuration only)
6. DataWedge v3.5.18
7. Fix for SPR 22059 - Data compression does not work on CE6 devices
8. Fix for SPR 19297 - The Login to Network Server dialog is not saving the password even though the option to save it is enabled after network disconnect and reconnect occurs
9. Fix for SPR 21697 - Serial communication fails in low baud rates

10. Fix for SPR 23727 - Increasing the Page Pool Memory Setting from 3MB to 5 MB for CE6.0 OS

11. Fix for SPR 22126 - Blue state tray icon does not show lock state when CTRL or ALT modifier is on.

CONTENTS

1. 2100c60AcpUP033423.zip OS Update Package v03.34.23 Software (Chinese Professional)

2. 2100c60AcpAB033423.APF MSP OS Update Package v03.34.21 Software (Chinese Professional)

3. 2100c60AcpOS033423.hex OS Image v03.34.23 (Chinese Professional)

4. 2100c60ActUP033423.zip OS Update Package v03.34.23 Software (Chinese Traditional)

5. 2100c60ActAB033423.APF MSP OS Update Package v03.34.21 Software (Chinese Traditional)

6. 2100c60ActOS033423.hex OS Image v03.34.23 (Chinese Traditional)

7. 2100c60AdeUP033423.zip OS Update Package v03.34.23 Software (German)

8. 2100c60AdeAB033423.APF MSP OS Update Package v03.34.21 Software (German)

9. 2100c60AdeOS033423.hex OS Image v03.34.23 (German)

10. 2100c60AfrUP033423.zip OS Update Package v03.34.23 Software (French)

11. 2100c60AfrAB033423.APF MSP OS Update Package v03.34.21 Software (French)

12. 2100c60AfrOS033423.hex OS Image v03.34.23 (French)

13. 2100c60AitUP033423.zip OS Update Package v03.34.230 Software (Italian)

14. 2100c60AitAB033423.APF MSP OS Update Package v03.34.21 Software (Italian)

15. 2100c60AitOS033423.hex OS Image v03.34.23 (Italian)



16. 2100c60AjpUP033423.zip OS Update Package v03.34.23 Software (Japanese)
17. 2100c60AjpAB033423.APF MSP OS Update Package v03.34.21 Software (Japanese)
18. 2100c60AjpOS033423.hex OS Image v03.34.23 (Japanese)
19. 2100c60AkoUP033423.zip OS Update Package v03.34.23 Software (Korean)
20. 2100c60AkoAB033423.APF MSP OS Update Package v03.34.21 Software (Korean)
21. 2100c60AkoOS033423.hex OS Image v03.34.23 (Korean)
22. 2100c60ApbUP033423.zip OS Update Package v03.34.23 Software (Portuguese Brazil)
23. 2100c60ApbAB033423.APF MSP OS Update Package v03.34.21 Software (Portuguese Brazil)
24. 2100c60ApbOS033423.hex OS Image v03.34.23 (Portuguese Brazil)
25. 2100c60AsiUP033423.zip OS Update Package v03.34.23 Software (Spanish)
26. 2100c60AsiAB033423.APF MSP OS Update Package v03.34.21 Software (Spanish)
27. 2100c60AsiOS033423.hex OS Image v03.34.23 (Spanish)

DEVICE COMPATIBILITY

This software release has been approved for use with the following Zebra devices.

Device	Operating System
MC2100	Windows CE 6.0 Core
MC2180	Windows CE 6.0 Core

INSTALLATION REQUIREMENTS

MC2100 device must contain a released version of CE 6.0 Core Software.



INSTALLATION INSTRUCTIONS

Update through\Storage Card

- Unzip 2100c60AxxUP033423.zip file and copy its contents (**OSUpdate** folder) to the root folder on SD card.
- Insert the SD card in the device to be updated.
- Place the device to be updated on A/C power supply.
- Run **2100c60Axx_SD** shortcut from **\Storage Card\OSUpdate** folder to start the update process.

Update through\Application

- Unzip 2100c60AxxUP033423.zip file and copy its content (**OSUpdate** folder) to the **\Application** folder.
- Place the device to be updated on A/C power supply.
- Run **2100c60Axx_App** shortcut from **\Application\OSUpdate** folder to start the update process.

Notes:

- Keep the device in AC Power during the update process.
- Updating through Temp folder is not supported in MC2100 due to RAM space constraints.
- While using Application partition update method, Application data will be kept intact and OSUpdate folder will also remain after completing the OS Update process.

PART NUMBER AND RELEASE DATE

2100c60AcpUP033423

2100c60AcpAB033423

2100c60AcpOS033423

2100c60ActUP033423

2100c60ActAB033423

2100c60ActOS033423

2100c60AdeUP033423

2100c60AdeAB033423

2100c60AdeOS033423

2100c60AfrUP033423

2100c60AfrAB033423

2100c60AfrOS033423



2100c60AitUP033423

2100c60AitAB033423

2100c60AitOS033423

2100c60AjpUP033423

2100c60AjpAB033423

2100c60AjpOS033423

2100c60AkoUP033423

2100c60AkoAB033423

2100c60AkoOS033423

2100c60ApbUP033423

2100c60ApbAB033423

2100c60ApbOS033423

2100c60AsiUP033423

2100c60AsiAB033423

2100c60AsiOS033423

September 30, 2013