



MC9090 OPERATING SYSTEM WINDOWS MOBILE BSP 01.10.00 RELEASE NOTES

INTRODUCTION

The Application Update Loader package 909Xw50LenAP000004.zip contains the software required to update a MC9090 device with critical fixes.

DESCRIPTION

Issues Resolved:

1. Corrected an issue where Imager sometimes stops to scan while using Picklist mode.
2. Corrected issue where the flash is continuously written before screen calibration, when device is clean booted and sits at windows mobile splash screen.
3. Corrected an issue where Serial Driver drops bytes of data in the serial stream.
4. Corrected an issue where MC9090S speakers are blown.
5. Nand Flash upgrade and Fusion version 2.55.1.0.016R

DEVICE COMPATIBILITY

This software release has been approved for use with the following Symbol devices

Device	Operating System
MC909x	Windows Mobile 5.0

RELEASE DATE

20th April, 2011