

# SHA2 SUPPORT FOR ALL ES405 MC659B MC45 PRODUCTS - SPR 26392 RELEASE NOTES

## INTRODUCTION

This patch addresses SPR26392 – VPA – SHA2 Support for all ES405 MC659B MC45 products. As part of fix, Microsoft released a new AKU 6.5.3.12.35 (build no. 29299) which contains the support for recognizing the SHA2 certificate through Cryptographic APIs (CAPIs).

## DESCRIPTION

- 1) This issue is seen on all ES405 MC659B MC45 devices running WEHH6.5. SHA2 certificate is not recognized properly and installing any root SHA2 certificate gets installed in intermediate section rather than root section. Also there was an issue syncing emails from Microsoft exchange server.
- 2) The latest OS hotfix image built with AKU35 solves the issue.

## CONTENTS

405Bw65XenUL604703.zip

659Bw65XenUL604703.zip

459Xw65XenUL601603.zip

## DEVICE COMPATIBILITY

This software release has been approved for use with the following Symbol devices.

Device	Operating System
ES400	Windows Mobile 6.5
MC65	Windows Mobile 6.5
MC45	Windows Mobile 6.5



## INSTALLATION REQUIREMENTS

- ES400 BSP 04.47.02 or earlier
- MC65 BSP 04.47.02 or earlier
- MC45 BSP 03.16.02 or earlier

## INSTALLATION INSTRUCTIONS

For NORMAL installation of the OS Hotfix image:

1. Unzip and copy the content to either \Temp or \Storage Card of the device.
2. Start the OS update by clicking the StartUpLdr.exe file.
3. StartUpLdr.exe will update the OS image and device will automatically coldboot.

## PART NUMBER AND RELEASE DATE

405Bw65XenUL604703.zip

659Bw65XenUL604703.zip

459Xw65XenUL601603.zip

November 25, 2014