


VC5090 Mounting Bracket Kit

Installation Instructions

The VC5090 Mounting Bracket Kit includes one (1) horizontal plate and two (2) spacers.



1. If installed, disconnect all cables from the VC5090 and remove it from the mounting bracket.
2. Remove the mounting bracket from the forklift.
3. Remove four nuts securing the horizontal plate to the left and right vertical arms.
4. Remove nuts, flat washers, grommets and bolts.
5. Discard the existing horizontal plate. Save all other hardware.
6. Reassembly with new horizontal plate and spacers as shown in the diagram above.
7. Torque the cap screws to 4.84 ± 0.23 kgf-m (420 ± 20 lbf-in.).



Zebra Technologies Corporation
Lincolnshire, IL U.S.A.
<http://www.zebra.com>

Zebra and the stylized Zebra head are trademarks of ZIH Corp., registered in many jurisdictions worldwide. All other trademarks are the property of their respective owners.

©2015 ZIH Corp and/or its affiliates. All rights reserved.



72-119689-02
Revision A — April 2015