

1) Carefully remove the trim panel as shown using trim panel removal tools to avoid damage.



2) There are many retaining clips so work slowly all around the edges to release.





3) Remove the upper right radio retaining screw as shown.



4) Remove the upper left radio retaining screw as shown.





5) Remove the lower right radio retaining screw as shown.



6) Remove the lower left radio retaining screw as shown.





7) Remove both heater control retaining screws. Only right hand screw is pictured.



8) Remove both switch panel retaining screws. Only left hand screw is pictured.





9) Remove the left hand fascia retaining screw as shown.



10) Remove the right hand fascia retaining screw as shown.





11) Remove the heater and switch panel units as shown.




12) Remove the radio head unit disconnecting all of the wiring looms shown.





13) Remove the right hand chassis retaining bolt as shown.



14) Remove the left hand chassis retaining bolt as shown.





15) Fit the Left Hand Side Bracket 032-02-0301 as shown. Temporarily secure in place using two screws removed in steps 4 and 6.




16) Ensure that the bracket is pushed firmly in the direction of the arrow as you tighten the screws.





17) Fit two self tapping screws 039-02-0423 in the positions indicated in red below. Note that the picture below only shows one screw.







18) Fit the fascia retaining screw removed in step 9 as shown. Note that the metal of the bracket is designed to bend and will be pulled in by the screw. Ensure that it is fully tightened.





19) Fit one self tapping screws 039-02-0423 into the side as shown.




20) Fit one self tapping screws 039-02-0423 into the side as shown.






21) Refit the chassis retaining bolt removed in step 14 as shown.



22) Note that the metal of the bracket is designed to bend and will be pulled in by the screw. Ensure that it is fully tightened.





23) Remove the lower screw which was temporarily fitted in step 15.



24) Remove the upper screw which was temporarily fitted in step 15.





25) Repeat steps 15 to 24 for the Right Side Bracket 032-02-0300 pictured below.






26) Replace the cable looms removed in step 12 and refit the radio head unit.



27) Refit the four radio retaining screws as shown.





28) Refit the heater control unit and secure with the left hand retaining screw as shown.



29) Refit the right hand retaining screw to the heater control unit as shown.





30) Refit the switch panel unit and secure with the left hand retaining screw as shown.



31) Refit the right hand retaining screw to the switch panel unit as shown.





32) The vehicle should now look like the below photograph and is ready to have the trim panel refitted.

Note that it may be necessary to bend out the two metal tabs indicated slightly to make fitting of the trim panel easier.





33) Once the trim panel is securely back in place, fit the Front Bracket 032-02-0299 as shown.

Use four screws TD503712 and four lock washers TD503481 in the positions shown and tighten securely.









34) Fit the Docking Station / Tilt & Rotate Assembly to the front bracket as shown using the provided M8 fasteners.

NOTE:- It may be necessary to temporarily remove the rubber edge strip to allow for correct fitment.

Ensure that the location lugs are correctly engaged before final tightening to prevent unwanted rotation.

