
Release Notes - RS507 - In HID Mode, RS507 is not available when reconnected from terminal side - SPR 27372

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Part Number and Release Date](#)

Introduction

In HID Mode, RS507 is not available when reconnected from terminal side

Description

Firmware version "**PAAACC21-005-R00D0**" fixes the issue.

Contents

Part number	Description	SW File
PAAACC21-005-R00	RS507 FW Product Code	PAAACC21-005-R00D0.DAT

Device Compatibility

This software release has been approved for use with the following Zebra device.

Device	Operating System
RS507	Micro OSII

Installation Requirements

1. RS507 scanner
2. Computer running Windows 7 or Windows XP with BT support.
3. PC tool Application RS507PCTOOL000103.exe.

Installation Instructions

- Upgrade latest firmware "**PAAACC21-005-R00D0.DAT**" to RS507 scanner using "[PC tool installation](#)" through Bluetooth stack.
- To upgrade latest firmware, please refer chapter '7' in page no [7 - 38] of "RS507 Hands-Free Imager Product Reference Guide".

Part Number and Release Date

NA

May 2015