
Release Notes RS507X PAAACS00-006-R02

Contents

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Downloadable Software included in this Release](#)

[Part Number and Release Date](#)

Introduction

This release addresses the issues known in S00-006-R01 release.

This firmware is compatible with both RS507X and legacy RS507 models.

Description

This release contains the following changes from the previous release S00-006-R01.

- Fixes high power consumption for RS507X but introduces very rare Bluetooth communication stall issue.
- Fixes HID data corruption issue when 123scan is used to configure.

Contents

Filename	Description
PAAACS00-006-R02D0.DAT	RS507X/RS507 firmware file.

Device Compatibility

This firmware is compatible with following devices:

Device	Comments
RS507X	All SKUs
RS507	All SKUs

Installation Requirements

This firmware may be installed on any compatible RS507X and RS507 devices.

Installation Instructions

Using a WT41N0 device:

1. Use the firmware update utility `\\Windows\FirmwareUpdate\FirmwareUpdate.exe`
2. Download the `PAAACS00-006-R02D0.DAT` firmware to the WT41N0 device. (e.g. `\\application\PAAACS00-006-R02D0.DAT`)
3. Connect the RS507X/RS507 scanner to the WT41N0 device via the cable or Bluetooth.
4. Launch the FirmwareUpdate utility.
5. Select the Yes or No to 'Is your scanner in Bluetooth mode?' dialog, depending on your connection method.
6. Click 'Firmware...' button and select the new firmware file (.DAT file).
7. Click 'Flash Scanner' button.
8. Download process will start.
9. Once download is complete, the scanner will reboot and flash the red/green LED fast during firmware update process.
10. You can launch FirmwareUpdate utility again to confirm the updated revision of the firmware.

Using the RS507 PC Tool Utility

1. Connect the RS507X/RS507 to PC via Bluetooth.
2. Start the RS507PCTool utility.
3. Open the COM port to the RS507X/RS507 (Refer to the RS507 user guide for more details on RS507PCTool usage).
4. Select the `PAAACS00-006-R02D0.DAT` files and select Update Firmware.

Downloadable Software Included in this Release

Filename	Description
PAAACS00-006-R02D0.DAT	Product Code for RS507X/RS507

Part Number and Release Date

PAAACS00-006-R02D0

01-05-2018