

---

# Release Notes RS507X PAAACS00-006-N01D0

## Contents

---

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Downloadable Software included in this Release](#)

[Part Number and Release Date](#)

## Introduction

---

This release is intended to provide SPR#39946 and SPR#40182 fixes available for all the customers via CFE. This firmware is built on top of R04 firmware. This firmware version provides solution to proximity alone mode of RS507 issue with Android host devices.

This firmware is compatible with both RS507X and legacy RS507 models.

## Description

---

This release includes the following changes from the previous release S00-006-R04.

### Fixes

- SPR#39946 Proximity issue fix
- SPR#40182 Intermittent beam stuck issue on RS507

# Contents

---

Filename	Description
PAAACS00-006-N01D0.DAT	RS507X/RS507 firmware file

## Device Compatibility

---

This firmware is compatible with following devices:

Device	Comments
RS507X	All SKUs
RS507	All SKUs

## Installation Requirements

---

This firmware may be installed on any compatible RS507X and RS507 devices.

## Installation Instructions

---

### Using a WT41N0 device:

1. Use the firmware update utility `Windows\FirmwareUpdate\FirmwareUpdate.exe`
2. Download the PAAACS00-006-N01D0.DAT firmware to the WT41N0 device. (e.g. `\application\PAAACS00-006-N01D0.DAT`)
3. Connect the RS507X/RS507 scanner to the WT41N0 device via the cable or Bluetooth.
4. Launch the FirmwareUpdate utility.
5. Select the Yes or No to 'Is your scanner in Bluetooth mode?' dialog, depending on your connection method.
6. Click 'Firmware...' button and select the new firmware file (.DAT file).
7. Click 'Flash Scanner' button.

8. Download process will start.
9. Once download is complete, the scanner will reboot and flash the red/green LED fast during firmware update process.
10. You can launch FirmwareUpdate utility again to confirm the updated revision of the firmware.

## Using the RS507 PC Tool Utility

1. Connect the RS507X/RS507 to PC via Bluetooth.
2. Start the RS507PCTool utility.
3. Open the COM port to the RS507X/RS507 (Refer to the RS507 user guide for more details on RS507PCTool usage).
4. Select the PAAACS00-006-N01D0.DAT files and select Update Firmware.

## Downloadable Software Included in this Release

---

<b>Filename</b>	<b>Description</b>
PAAACS00-006-N01D0.DAT	Product Code for RS507X/RS507

## Part Number and Release Date

---

PAAACS00-006-N01D0

08-20-2020