
Release Notes – MC32N0 CE 7.0 Chinese Hotfix OS v61.57.20

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Release Date](#)

Introduction

SPR32707 – Unable to display Chinese font on IE browser when using dropdown and combo box list

This Hot Fix OS v61.57.20 is based on BSP v10.57.12

Description

Resolved an issue wherein Chinese fonts are not displaying on IE browser when using dropdown and combo list by updating an image 32N0c70BcpUC615720.zip

Contents

32N0c70BcpUC615720.zip - OSUpdate Package for MC32N0 CE devices including Clean Application

Device Compatibility

This HotFix OS Package software release has been approved for use with the following Zebra devices.

Device	Operating System	BSP Version
MC32N0	CE 7.0	Chinese Simplified v10.57.12

Installation Requirements

MC32N0 device must contain a released version of CE 7.0

Installation Instructions

1. Unzip the "32N0c70BcpUC615720.zip" files and copy its content to the \Temp folder.
2. Place the device to be upgraded on A/C power supply.
3. Navigate to the \temp\OSUpdate folder and invoke the 32N0c70Bcp_TEMP shortcut.
4. The update will take about 3-4 minutes to complete. Please do not remove the device from A/C power during this time.

OR

1. Unzip the "32N0c70BcpUC615720.zip" files and copy its content to the \Storage Card folder.
2. Place the SD card in the device to be upgraded.
3. Place the device to be upgraded on A/C power supply.
4. Navigate to the \Storage Card\OSUpdate and invoke the 32N0c70Bcp_SD shortcut.
5. The update will take about 3-4 minutes to complete. Please do not remove the device from A/C power during this time.

Part Number and Release Date

N/A

November, 2017