

Release Notes - MC55A0 - scanner enabled when inserted in cradle (Japanese & Korean OS) - SPR 25663

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Part Number and Release Date](#)

Introduction

This release contains the fix for SPR 21805 (scanner is triggered when put in cradle) applicable for Japanese and Korean OSes.

Description

1. SPR 25663 - Resolves an issue where the scanner is triggered when device is put in cradle and datawedge is enabled. Fix for SPR 21805 is applicable for English OS only. This release contains the same fix for Japanese and Korean OS.
2. It is to be noted that fix will not work if cradle is not connected to A/C power or to PC through USB connection. Also left trigger will remain disabled as long as device is on the cradle even when fix is applied.
3. If an application or the user cleans up 'Application' folder, this .cab solution has to be re-installed.
4. This fix is required only for MC55A0 devices manufactured before June 2012 (Rev A HW). It must NOT be applied to devices manufactured on or after June 2012 (Rev B HW).

Contents

SPR25663_MC55A0_Left_Trigger_Disable_After_500_WithReboot_Jp.cab
SPR25663_MC55A0_Left_Trigger_Disable_After_500_NoReboot_Jp.cab
SPR25663_MC55A0_Left_Trigger_Disable_After_500_WithReboot_Ko.cab
SPR25663_MC55A0_Left_Trigger_Disable_After_500_NoReboot_Ko.cab

Device Compatibility

This software release has been approved for use with the following Symbol devices.

Device	Operating System
MC55A0	Windows Mobile 6.5

Installation Requirements

- MC55A0 OS Version 01.34.0005
- MC55A0 OS Version 02.41.0003

Installation Instructions

For NORMAL installation of the PATCH:

1. Copy "SPR25663_MC55A0_Left_Trigger_Disable_After_500_WithReboot_Jp.cab" file for Japanese OS or "SPR25663_MC55A0_Left_Trigger_Disable_After_500_WithReboot_Ko.cab" file for Korean OS to the device.
2. Deploy the solution by tapping on the .cab file.
3. After successful deployment of the .cab file, device will do an automatic warm boot.

For MSP or REMOTE installation of the PATCH:

Use "SPR25663_MC55A0_Left_Trigger_Disable_After_500_NoReboot_Jp.cab" file for Japanese OS or "SPR25663_MC55A0_Left_Trigger_Disable_After_500_NoReboot_Ko.cab" file for Korean OS. This cab will not perform an automatic warm boot. MSP/Remote Installer is responsible for performing the warm boot

Part Number and Release Date

SPR25663_MC55A0_Left_Trigger_Disable_After_500_WithReboot_Jp.cab
SPR25663_MC55A0_Left_Trigger_Disable_After_500_NoReboot_Jp.cab
SPR25663_MC55A0_Left_Trigger_Disable_After_500_WithReboot_Ko.cab
SPR25663_MC55A0_Left_Trigger_Disable_After_500_NoReboot_Ko.cab
June 3, 2014