
Release Notes – VC70 CE 7.0 – Added support for Extended Function Keys (F13 to F24) in USB keyboard driver - SPR33042

Contents

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Release Date](#)

Introduction

SPR33042 - Added support for Extended Function Keys (F13 to F24) in USB keyboard driver.

Description

VC70 CE7 USB Keyboard driver is updated to add support for extended function keys F13 to F24 per USB HID specification. The new VC USB keyboards (KYBD-QW-VC-01 and KYBD-AZ-VC-01) requires new driver to support extended function keys with VC70 devices.

Contents

SPR33042_VC70_C70_v055703_en_WB_v1_0.cab (HotFix package with auto Warm boot)

SPR33042_VC70_C70_v055703_en_NB_v1_0.cab (HotFix package without auto Warm boot)

Device Compatibility

This HotFix Package software release has been approved for use with the following Zebra devices.

Device	Operating System	BSP Version
VC70	CE 7.0	v05.57.03

Installation Requirements

This SW is intended for VC70 CE7 devices with BSP v05.57.03

Installation Instructions

For Normal installation of the PATCH:

1. Copy "SPR33042_VC70_C70_v055703_en_WB_v1_0.cab" file to the application folder/SD card on the device by using Microsoft Active Sync or Mobile Device Center.
2. Navigate on the device to the application folder/SD card.
3. Deploy the solution by tapping on the "SPR33042_VC70_C70_v055703_en_WB_v1_0.cab" file.
4. After successful deployment of the "SPR33042_VC70_C70_v055703_en_WB_v1_0.cab" file, device will do an automatic warm boot.

For MSP or REMOTE installation of the PATCH:

1. Set up MDM (MSP, SOTI, Airwatch, etc..) to send "SPR33042_VC70_C70_v055703_en_NB_v1_0.cab " file to the application folder of the device.
2. To deploy the solution, setup in MDM to install the cab file "SPR33042_VC70_C70_v055703_en_NB_v1_0.cab" file.
3. Changes will take effect after a manual reboot of the terminal or if MDM reboots device.

Release Date

September, 2017