

Release Notes - WT41N0 CE 7.0 - BSP v03.54.02 - HotFix CFE v01.01.00 Package

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Release Date](#)

Introduction

HotFix CFE (Cumulative Fixes from Engineering) Package includes multiple SPR Hotfixes contained into a single package. The HotFix CFE Package helps the end users to keep up to date with all the SPR hotfixes for given product software release / revision.

HotFix CFE packages are validated only by engineering validation team and the package follows Zebra Technologies HotFix Package Policy. Click here to view HotFix Package Policy. [HotFix Support Policy](#)

Description

The content and related Hotfix that are included in this HotFix CFE_WT41_CE_035402_EN_v010100_e.cab is as follows.

SPR No	Synopsis
27525	Unable to Pair RS507 using Telnet Client

Package Details

CFE_WT41_CE_035402_EN_v010100_e.cab (CFE package without Warm boot)

Device Compatibility

This HotFix CFE Package software release has been approved for use with the following Zebra devices.

Device	Operating System	BSP Version
WT41N0	CE 7.0	v03.54.02

Installation Requirements

The HotFix CFE cab can be deployed to the Mobile device through below mentioned methods. For installing the cab, the users should have below mentioned tools.

- Windows Mobile Device Center (For Windows Desktops)
-

Installation Instructions

- Windows Mobile Device Center (For Windows Desktops)
 - Copy "CFE_WT41_CE_035402_EN_v010100_e.cab" file to the Application folder on the device.
 - Deploy the solution by tapping on the "CFE_WT41_CE_035402_EN_v010100_e.cab" file.
 - Change will take effect after manual reboot of the terminal is done.
-

Release Date

May, 2015
