
Release Notes - WAP4 WEH 6.5 OS Image v4.3

Contents

[Description](#)

[Device Compatibility](#)

[Component Contents](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Downloadable Software included in this Release](#)

Description

The following issues have been resolved in this CFE:

SPR NO	Synopsis
33679, 33926	Fixed exception which caused slow terminal response after switching from DataWedge to SCS.

Device Compatibility

This software release has been approved for use with the following Zebra devices.

Device	Operating System
Workabout Pro 4 (7528)	Windows Embedded Handheld 6.5.3

Component Contents

N/A

Installation Requirements

If previously installed, uninstall '7528 Release 2.3 OS Patch v1.1'.

Installation Instructions

To **uninstall** 7528 Release 2.3 OS Patch v1.1, follow the procedure below:

1. Delete contents of \Application\iinit folder.
2. Clean start device or update operating system software.

To update the operating system software of the WAP 4, follow the procedure below:

1. **If previously installed, uninstall '7528 Release 2.3 OS Patch v1.1' (Instructions above).**
2. The firmware can be upgraded using a USB Memory Stick or using a microSD Card.
3. The firmware file must be renamed 7528os.img
4. Copy the file containing the firmware upgrade and the Add-On cab file to the root directory of the USB memory stick or Micro SD card.
5. Install the USB memory stick into the docking cradle or install the Micro SD card into the WAP 4 in the Micro SD slot in the battery compartment
6. Press and hold down the [Blue FN] key, the [SCAN] key and the [Power] key, simultaneously for a minimum of six seconds.
7. When the update is complete, the device reboots to the main operating system.
8. Using File Explorer, locate and double click the Add-On cab file to begin installation.
9. When the Add-On cab update is complete, the device reboots to the main operating system.
10. Remove the MicroSD card from the device to prevent the device from performing the upgrade process again on the next cold boot, and then disconnect external power. The device is now ready to be used.

Downloadable Software Included in this Release

Filename	Description
P728XW65CPCB040300.CAB	WAP4 Windows Embedded Handheld Addon Cab File CFE Simplified Chinese V4.3
P728XW65CPMI040300.IMG	WAP4 Windows Embedded Handheld OS image CFE Simplified Chinese Image V4.3
P728XW65CTCB040300.CAB	WAP4 Windows Embedded Handheld Addon Cab File CFE Traditional Chinese V4.3
P728XW65CTMI040300.IMG	WAP4 Windows Embedded Handheld OS image CFE Traditional Chinese Image V4.3
P728XW65DECB040300.CAB	WAP4 Windows Embedded Handheld Addon Cab File CFE German V4.3
P728XW65DEMI040300.IMG	WAP4 Windows Embedded Handheld OS image CFE German Image V4.3
P728XW65ENCB040300.CAB	WAP4 Windows Embedded Handheld Addon Cab File English V4.3
P728XW65ENMI040300.IMG	WAP4 Windows Embedded Handheld OS image CFE English Image V4.3

P728XW65FRCB040300.CAB	WAP4 Windows Embedded Handheld Addon Cab File CFE French V4.3
P728XW65FRMI040300.IMG	WAP4 Windows Embedded Handheld OS image CFE French Image V4.3
P728XW65ITCB040300.CAB	WAP4 Windows Embedded Handheld Addon Cab File Italian V4.3
P728XW65ITMI040300.IMG	WAP4 Windows Embedded Handheld OS image CFE Italian Image V4.3
P728XW65JPCB040300.CAB	WAP4 Windows Embedded Handheld Addon Cab File Japanese V4.3
P728XW65JPMI040300.IMG	WAP4 Windows Embedded Handheld OS image CFE Japanese Image V4.3
P728XW65KOCB040300.CAB	WAP4 Windows Embedded Handheld Addon Cab File CFE Korean V4.3
P728XW65KOMI040300.IMG	WAP4 Windows Embedded Handheld OS image CFE Korean Image V4.3
P728XW65SICB040300.CAB	WAP4 Windows Embedded Handheld Addon Cab File Spanish V4.3
P728XW65SIMI040300.IMG	WAP4 Windows Embedded Handheld OS image CFE Spanish Image V4.3

Last Revised: 07/10/18