
Release Notes <WAP4 WinCE 6 OS Image><v3.4>

Contents

[Description](#)

[Device Compatibility](#)

[Component Contents](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Downloadable Software included in this Release](#)

Description

The following issues have been resolved in this CFE:

SPR NO	Synopsis
28835	Improve GPS receiver accuracy when device is stationary.
30174	Corrected behavior of Network LAN taskbar icon when using quad dock.
30320	Improve Battery Health indicator for batteries no longer supported or recognized.
30611	Allow the use of external Bluetooth GPS devices.

Device Compatibility

This software release has been approved for use with the following Zebra devices.

Device	Operating System
Workabout Pro 4 (7528)	Windows CE 6.0 Professional

Component Contents

N/A

Installation Requirements

If previously installed, uninstall '7528 Release 2.3 OS Patch v1.1'.

Installation Instructions

To **uninstall** 7528 Release 2.3 OS Patch v1.1, follow the procedure below:

1. Delete contents of \Application\Tiinit folder.
2. Clean start device or update operating system software.

To update the operating system software of the WAP 4, follow the procedure below:

1. **If previously installed, uninstall '7528 Release 2.3 OS Patch v1.1' (Instructions above).**
2. The firmware can be upgraded using a USB Memory Stick or using a microSD Card.
3. The firmware file must be renamed 7528os.img
4. Copy the file containing the firmware upgrade to the root directory of the USB memory stick or Micro SD card
5. Install the USB memory stick into the docking cradle or install the Micro SD card into the WAP 4 in the Micro SD slot in the battery compartment
6. Press and hold down the [Blue FN] key, the [SCAN] key and the [Power] key, simultaneously for a minimum of six seconds.
7. When the update is complete, the device reboots to the main operating system.
8. Remove the MicroSD card from the device to prevent the device from performing the upgrade process again on the next cold boot, and then disconnect external power. The device is now ready to be used.
9. Install add-on cab file.

Downloadable Software Included in this Release

Filename	Description
P728XC60CTMI030400.IMG	WAP4 Windows CE OS image CFE Traditional Chinese v3.4
P728XC60CPMI030400.IMG	WAP4 Windows CE OS image CFE Simplified Chinese v3.4
P728XC60EFMI030400.IMG	WAP4 Windows CE OS image CFE ENG/FRA/GER/ITA/ESN v3.4

P728XC60JPMI030400.IMG	WAP4 Windows CE OS image CFE Japanese v3.4
P728XC60KOMI030400.IMG	WAP4 Windows CE OS image CFE Korean v3.4

Last Revised: <12-21-2016>