Release Notes - Hotfix CFE for Imager Scanning Performance Improvements on MC2180 CE Pro BSP v82.34.04

Introduction

Description

Package Details

Device Compatibility

Installation Requirements

Installation Instructions

Release Date

Introduction

HotFix CFE (Cumulative Fixes from Engineering) Package includes multiple SPR Hotfixes contained into a single package. The HotFix CFE Package helps the end users to keep up to date with all the SPR hotfixes for given product software release / revision.

HotFix CFE packages are validated only by engineering validation team and the package follows Zebra Technologies HotFix Package Policy. Click here to view HotFix Package Policy. HotFix Support Policy

Description

The content and related Hotfix included in this HotFix CFE_MC21_CE_823404_EN_v010100_e.cab is as follows

SPR No	Synopsis
26412	Scanner Decoding Performance Improvement for Imager based devices

Package Details

CFE MC21 CE 823404 EN v010100 e.cab (CFE package without Warm boot)

Device Compatibility

This HotFix CFE Package software release has been approved for use with the following Zebra devices.

Device	Operating System	BSP Version
MC2180 Pro	CE 6.0	v82.34.04

Installation Requirements

The HotFix CFE cab can be deployed to the Mobile device through any one of the below mentioned methods. For installing the cab, the users should have at least one of the below mentioned tools.

- Windows Mobile Device Center (For Windows Desktops)
- SD Cards / Micro SD cards
- MDM set up

Installation Instructions

For Normal installation of the PATCH:

- Windows Mobile Device Center (For Windows Desktops) Installation Instructions:
 - 1. Copy "CFE_MC21_CE_823404_EN_v010100_e.cab" file to the application folder on the device.
 - 2. Deploy the solution by tapping on the "CFE_MC21_CE_823404_EN_v010100_e.cab" file.
 - 3. Change will take effect after manual reboot of the terminal is done.
- SD Cards / Micro SD cards Installation Instructions:
 - 1. Copy "CFE MC21 CE 823404 EN v010100 e.cab" file to the SD card.
 - 2. Deploy the solution by tapping on the "CFE MC21 CE 823404 EN v010100 e.cab"
 - 3. Change will take effect after manual reboot of the terminal is done.

For MSP or REMOTE installation of the PATCH:

- Set up MDM (MSP, Soti, Airwatch, etc..) to send "CFE_MC21_CE_823404_EN_v010100_e.cab" file to the application folder of the device.
- 2. To deploy the solution, setup in MDM to install the cab file "CFE MC21 CE 823404 EN v010100 e.cab" file.
- 3. Changes will take effect after a manual reboot of the terminal or if MDM reboots device.

Release Date

June, 2015