

MC45 OPERATING SYSTEM BSP 02.13.1001 - HOTFIX CFE 1.0 RELEASE NOTES

INTRODUCTION

This package contains the v02.13.1001 English OS images for the MC45 terminals which are running with WEHH 6.5.3 operating system.

This image supersedes the older images.

DESCRIPTION

Changes since BSP 02.13.0000:

General Stability/Exceptions/Crashes/Lockups

SPR24853 – Resolved an issue where the device would freeze on one of the bootup splash screens and fail to complete bootup, and would require a reload of the OS to function.

Note:

The OS update package does not wipe the application folder. If it is preferred to wipe the Application folder during the OS update, the CleanAppl.bin command should be added to the pkgs.lst file. The CleanAppl.bin file is already included in the OS Update package.

CONTENTS

HotFix_MC45_BSP13.1001EN_SPR24853.zip - Update Loader images for English OS 02.13.1001

DEVICE COMPATIBILITY

This software release has been approved for use with the following devices.

Device	Operating System
MC45	Windows Mobile 6.5.3

INSTALLATION REQUIREMENTS

This software package has been approved for use with the following:

Microsoft Windows 2000 or Windows XP Operating System.

ActiveSync 4.5 or higher.

If developing applications for Windows Mobile 6.5

MC45 currently running English Rev A BSP01.09.0414,REV B 02.13.0000.

INSTALLATION INSTRUCTIONS

Copy contents of zip file to SD card or to \Temp folder. Execute StartUpdLdr.exe or cold boot terminal by pressing 1 + 9 + pwr and hold the left trigger key to start the update loader process.

PART NUMBER AND RELEASE DATE

HotFix_MC45_BSP13.1001EN_SPR24853.zip

May 23, 2014