
Release Notes – MC65 WM 6.5 BSP v65.48.02 - Silently importing certificates are not working - SPR33337

Contents

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

Introduction

SPR33337 – Silently importing certificates into the device is not working.

Description

The package “659Bw65XenUL654802.zip” provides a fix where in silent installation of certificates are not working, pop up message will prompt for confirmation.

Contents

659Bw65XenUL654802.zip (Update Loader release with silently importing certificates)

Device Compatibility

This HotFix Package software release has been approved for use with the following Zebra devices.

Device	Operating System	BSP Version
MC65	WM 6.5	v5.48.02

Installation Requirements

This SW is intended for MC65 WM 6.5 devices with OS v65.48.02

Installation Instructions

1. Copy contents of zip file "659Bw65XenUL654802.zip" to SD card or to \Temp folder.
2. Execute StartUpdLdr.exe or cold boot terminal by pressing 1 + 9 + power button and hold the left trigger key to start the update loader process.