

Release Notes - MC909x WM6.1 BSP9 Critical Fixes

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Instructions](#)

[Release Date](#)

Introduction

The Application Update Loader package 909XW61LenAP000002.zip contains the software required to update a MC909x device with critical fixes.

Description

Issues Resolved:

1. Corrected an issue where MC9090-S speakers are blown.
2. Corrected an issue where MC909X running WM6.1 and iDockIt v 5.02.00 fails to complete file downloads via Internet Explorer when in CRD9000-40001E Ethernet cradle.
3. Nand Flash upgrade
4. Corrected an issue where Remote Desktop missing from WM6.1

Contents

909XW61LenAP000002.zip

Device Compatibility

This software release has been approved for use with the following Symbol devices.

Device	Operating System
MC909x	Windows Mobile 6.1

Installation Instructions

1. Download and unzip the file ‘**909XW61LenAP000002.zip**’ to temp folder or storage card.
2. Double click on the application “StartUpLdr.exe”.
3. Wait for few minutes, update will get installed automatically.

Release Date

Release Date: 05th Dec, 2011