

Hotfix for the issue that the MT20x0 adds a character to the end of some Aztec barcodes.

[Part #:]

Contents

- [Description](#)
 - [Device Compatibility](#)
 - [Release Notes](#)
 - [Components](#)
 - [Installation](#)
 - [Notes](#)
 - [Late Additions](#)
-

Description

Thank you for selecting Motorola as your mobility solution tool provider.

This hotfix fixes the issue that the MT20x0 adds a character to the end of some Aztec barcodes.

[Back to Top](#)

Device Compatibility

This Hotfix applies to following Motorola products:

- MT2090
- MT2070

[Back to Top](#)

Release Notes

Version v1.0

- This hotfix fixes the issue that, that the MT20x0 adds a character to the end of some Aztec barcodes.

[Back to Top](#)

Components

The installed files should be in the following folder on the scanner.

Component	Location
PixDLL.dll	\Platform\
PixDLL.cpy	\Platform\

[Back to Top](#)

Installation

The following is the procedure to apply the Hotfix. It is assumed that the ActiveSync installed on the PC.

- 1) ActiveSync the scanner to a PC;
- 2) Open up the “Platform” folder on the device using “Explore” on ActiveSync;
- 3) Copy the PixDLL.dll and PixDLL.cpy files to “\Platform” folder;
- 4) Cold boot the scanner (by press and hold scan trigger and ‘2’ key. Wait for screen going black the 2nd time and release the trigger and key. Or, just remove the battery and reinsert it to cold boot.)

The scanner should boot up with the Hotfix applied.

[Back to Top](#)

Notes

[Back to Top](#)

Late Additions

[Back to Top](#)

Last revised: August 27, 2010

*Copyright (c) 2003-2010
Motorola, Inc.*