

# Release Notes - SB1- PTT Express device pops up lsp stability warning low error message - SPR 25783

---

- [Introduction](#)
  - [Description](#)
  - [Contents](#)
  - [Device Compatibility](#)
  - [Installation Requirements](#)
  - [Installation Instructions](#)
  - [Part Number and Release Date](#)
- 

## Introduction

This patch resolved the following issue: SB1 PTT Express – Warning message "LSP\_STABILITY WARNING LOW" appears on the device while making Call.

## Description

1. This issue is observed on SB1 device when a call is initiated. The warning message displayed doesn't get closed until the device is rebooted .This issue occurs intermittently.
2. The SPR25783\_PTT.apf package consists of the PTT client version 1.1.69.0000 provided by the PTT software team.

## Contents

SPR25783\_PTT.apf

## Device Compatibility

This software release has been approved for use with the following Symbol devices.

Device	Operating System
SB1	Windows CE 6.0

## Installation Requirements

- SB1 OS Version 36.3
- SB1 OS Version 39.6

## Installation Instructions

MSP installation procedure has to be used to deploy this PATCH,

To install SPR25783\_PTT.apf

- 1) Configure the MSP using "SPR25783\_PTT.apf" and generate the barcode.
- 2) On the Device Go to Settings>More Settings>Advance settings
- 3) Go to RD Client and scan the barcode label.
- 4) Wait for the package installation to complete.

If patch is applied on OS Version 36.3 and then OSUpdate is done with OS 39.6, this patch needs to be reapplied.

## Part Number and Release Date

SPR25783\_PTT.apf  
July 10, 2014