

7527_WM61_6.5.1251**Software Release Notice**

5/19/2016

Release Date: 2016.05.19

Release Images: Part #**Released @ Iteration 2**

7527_WM61_CLA_FRA_MULTI_6.5.1251_E166I [1098971]
 7527_WM61_CLA_GERMAN_DEU_MULTI_6.5.1251_E166I [1098987]
 7527_WM61_CLA_ITAL_MULTI_6.5.1251_E166I [1098985]
 7527_WM61_CLA_JAP_MULTI_6.5.1251_E166I [1098973]
 7527_WM61_CLA_KOR_MULTI_6.5.1251_E166I [1098989]
 7527_WM61_CLA_SCH_MULTI_6.5.1251_E166I [1098975]
 7527_WM61_CLA_SPA_ESN_MULTI_6.5.1251_E166I [1098977]
 7527_WM61_CLA_TCH_MULTI_6.5.1251_E166I [1098983]
 7527_WM61_CLA_WWE_MULTI_6.5.1251_E166I [1098979]
 7527_WM61_PRO_FRA_MULTI_6.5.1251_E166I [1098972]
 7527_WM61_PRO_GERMAN_DEU_MULTI_6.5.1251_E166I [1098988]
 7527_WM61_PRO_ITAL_MULTI_6.5.1251_E166I [1098986]
 7527_WM61_PRO_JAP_MULTI_6.5.1251_E166I [1098974]
 7527_WM61_PRO_SCH_MULTI_6.5.1251_E166I [1098976]
 7527_WM61_PRO_SPA_ESN_MULTI_6.5.1251_E166I [1098978]
 7527_WM61_PRO_TCH_MULTI_6.5.1251_E166I [1098984]
 7527_WM61_PRO_WWE_MULTI_6.5.1251_E166I [1098980]

Release History:

7527_WM61_CLA_TCH_MULTI_6.4.1097 (WM61.1097.1 Released@2014-05-13)
 7527_WM61_CLA_FRA_MULTI_5.0.798 (WM61.798.4 Released@2010-02-17)
 7527_WM61_CLA_WWE_MULTI_5.0.798 (WM61.798.3 Released@2010-02-17)
 7527_WM61_CLA_FRA_MULTI_4.0.786 (WM61.786.4 Released@2009-11-12)
 7505_WM61_PRO_FRA_4.0.786 (WM61.786.1 Released@2009-10-30)
 7527_WM61_PRO_FRA_MULTI_3.0.741 (WM61.741.4 Released@2009-08-20)
 7527_UPGRADE_TO_CE5_MULTI_4.0.741 (WM61.741.2 Released@2009-08-04)
 7505_WM61_CLA_KOREAN_2.1.724 (WM61.724.1 Released@2009-05-07)
 7527_WM61_CLA_WWE_1.0.659 (WM61.659.5 Released@2009-03-09)
 7505_WINCE_5_MULTI_4.0.626 (7505.626.4 Released@2008-11-06)
 7505_WINCE_5_MULTI_3.0.598 (7505.598.5 Released@2008-07-21)
 7505_WINCE_5_MULTI_2.0.585 (7505.585.1 Released@2008-05-09)
 7505_WINCE_5_MULTI_0.4.578 (7505.578.3 Released@2008-04-15)
 7505_WINCE_5_MULTI_0.3.568 (7505.568.2 Released@2008-03-18)
 7505_WINCE_5_MULTI_0.1.536 (7505.536.4 Released@2008-02-19)

Build Dependencies:

7527BooSt - Signed Ultrasecure [5.5.1081]
 7527uC_Keyboard ~ 797.2_A110o
 7527uC_Power ~ 797.2_A110o
 AKU 1.5.75
 Component BTRestore Tools.711.1 [3.0.711_C099o] ~
 components/BTRestore/BTRestore_WM5.zip 1.2
 Component TotalRecall : 3.1.735_G079o ~ components/TotalRecall/TotalRecall_WM5.zip 1.6
 Component WWAN : 793.3_A140r ~ components/wwan/WWAN_WM5.zip 1.7

SOFTWARE CHANGES

This section provides a list of software changes made since the last Release.

0 *check-in(s), that is/are italic, has/have configuration or parameter changes.*

1251.1

[SCR-38365: WAP Quad Dock Design with New LAN9500A USB IC](#)

[- SCR-38365 \(7527pocketpc\) Added ax88178, ax88772 and smsc9500 driver to WAP3 \(7257pocketpc\)](#)

1251.2

[SCR-38365: WAP Quad Dock Design with New LAN9500A USB IC](#)

[- SCR-38365 \(7527pocketpc\) Added ax88178, ax88772 and smsc9500 driver to WAP3 \(7257pocketpc\)](#)

[- SCR-38365 \(bohicawince\) Added XIP regions](#)

This document is proprietary and as such cannot be disclosed, used, copied, or transmitted without prior consent of Psion Inc.

Copyright Psion Inc. 2016.