
Release Notes - <TC55 Reset Packages for the MSP deployment >

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Part Number and Release Date](#)

Introduction

These packages will put the terminal into default factory settings

Description

The T55N0JB0VAFEN14500.apf contains MSP deployment package to perform factory reset on the terminal.

The T55N0JB0VAEEN14500.apf contains MSP deployment package to perform factory reset on the terminal and it will not erase the Enterprise folder.

Contents

1. T55N0JB0VAEEN14500.apf– A MSP Enterprise Reset update package
2. T55N0JB0VAFEN14500.apf– A MSP Factory Reset update package

Device Compatibility

This software release has been approved for use with the following devices.

Device Part Number	Operating System
TC55	JellyBean 4.1.2

Installation Requirements

- TC55 device must be running with Android JellyBean operating system
- Mobility Service Platform

Installation Instructions

1. Please refer Mobility Service Platform deployment guide for instruction.
2. Upload MSP package to the MSP server
3. Connect the device to Wi-Fi network which is connected to MSP server.
4. On the device launch the MSP Rapid Deployment App located in the Apps section.
5. Click on Scan Barcodes and scan barcodes

Part Number and Release Date

T55N0JB0VAEEN14500
T55N0JB0VAFEN14500

October 20, 2013