

---

# **Release Notes - <TC55 KK Reset Packages for the MSP deployment >**

---

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Part Number and Release Date](#)

---

## **Introduction**

These packages will put the terminal into default factory settings

## **Description**

The T55N0KXXVAFEN25202.apf contains MSP deployment package to perform factory reset on the terminal.

The T55N0KXXVAEEN25202.apf contains MSP deployment package to perform factory reset on the terminal and it will not erase the Enterprise folder.

## **Contents**

1. T55N0KXXVAEEN25202.apf– A MSP Enterprise Reset update package
2. T55N0KXXVAFEN25202.apf– A MSP Factory Reset update package

## **Device Compatibility**

This software release has been approved for use with the following devices.

<b>Device Part Number</b>	<b>Operating System</b>
TC55	Android KitKat 4.4.3

## **Installation Requirements**

- TC55 device must be running with Android KitKat operating system
- Mobility Service Platform

## **Installation Instructions**

1. Please refer Mobility Service Platform deployment guide for instruction.
2. Upload MSP package to the MSP server
3. Connect the device to Wi-Fi network which is connected to MSP server.
4. On the device launch the MSP Rapid Deployment App located in the Apps section.
5. Click on Scan Barcodes and scan barcodes

## **Part Number and Release Date**

T55N0KXXVAFEN25202  
T55N0KXXVAEEN25202

April 30, 2015