

RS507 FIRMWARE FAILED TO DECODE QR BARCODES RELEASE NOTES - SPR 31114

INTRODUCTION

SPR 31114 - RS507 Failed to decode QR barcodes.

DESCRIPTION

This SPR fix resolves the QR barcode decoding issue.

CONTENTS

Part Number	Description	SW File
PAAACS00-005-R08	RS507 FW Product Code	PAAACS00-005-R08D0.DAT

DEVICE COMPATIBILITY

This software release has been approved for use with the following devices:

Device	Operating System
RS507	Micro OS-II

INSTALLATION REQUIREMENTS

- RS507 scanner.
- Computer running Windows 7 or Windows XP with BT support.
- PC tool Application RS507PCTOOL000103.exe.

INSTALLATION INSTRUCTIONS

- Upgrade latest firmware "PAAACS00-005-R08D0.DAT to RS507 scanner using "[PC tool installation](#)" through Bluetooth stack.
- Refer to "[HID Keyboard Keystroke Delay](#)" for configuring RS507 Inter character HID Keyboard Keystroke Delays (0ms or 20ms or 40ms).
- To upgrade latest firmware, please refer chapter '7' in page no [7 - 38] of "[RS507 Hands-Free Imager Product Reference Guide](#)".

PART NUMBER AND RELEASE DATE

N/A

February 2017