

ET5X OPERATING SYSTEM BSP

01.00.10 RELEASE NOTES

INTRODUCTION

The ET50/55 marries the best of consumer-styling with all the enterprise-class features you need to increase workforce productivity, with a real business class return on your tablet investment. Your workers get the elegant personal tablet styling they want, while you get a durable tablet designed to last for years, exceptional battery power, rapid capture of business data, plus a comprehensive family of business accessories to easily customize a solution for any job.

DESCRIPTION

1. Windows Embedded 8.1 Industry Pro (6.3.9600.16384).
2. Insyde Baytrail Bios V05.04.16.0044.
3. Intel Baytrail Bios FRC V1.8.2.
4. Intel Baytrail TXE FW V1.0.6.1120.
5. Intel Baytrail Drivers VWW14_2014 PR1.
6. Huawei LTE V11.350.16.17.00.
7. Sierra Wireless modem FW V4.3.1.6
8. WIFI V5.93.98.187.
9. BT V12.0.0.9190.
10. GPS V20.22.405.18.
11. NFC V6.5.9.0.
12. 3G Modem V6.3.9600.16384.
13. ULPMC ULPMC_64_08.

CONTENTS

WIN8-ZEBRA-R1.0-010-x64-autoinstaller-zebraKey.zip :Complete OS update image with the detailed instructions on how to flash the image.

DEVICE COMPATIBILITY

This software release has been approved for use with the following Symbol devices.

Device	Operating System
ET50	Windows Embedded 8.1 Industry Pro
ET55	Windows Embedded 8.1 Industry Pro



INSTALLATION REQUIREMENTS

ET5X device must contain a released version of Windows Embedded 8.1 Industry Pro

INSTALLATION INSTRUCTIONS

Please see Zebra ET5X Windows Flashing Instructions.docx which is part of WIN8-ZEBRA-R1.0-010-x64-autoinstaller-zebraKey.zip.

NOTE: Additional reboot is required after performing the OS Update.

CHANGES AND FIXES

-Support for 8" and 10" Non Scan Expansion Backs [ZBK-ET5X-8RH1-01 or ZBK-ET5X-10RH1-01].

- Updated Expansion pack system tray application 1.0.8.

- Updated windowsdeviceservice 1.0.1.1

- Updated ULPMC to 64_08.

- Removed scanner SDK.

PART NUMBER AND RELEASE DATE

5xxxW81xenOS010010

Mar 29, 2016