

ES405B - ENGLISH HOTFIX OS RELEASE V03.44.1001 (NON SPRINT BRANDED) - SPR 24853 RELEASE NOTES

INTRODUCTION

This package contains the v03.44.1001 OS image for the ES405B terminals which are running with WEHH 6.5.3 operating system.

This image supersedes the previous BSP44.0004 image and older images.

DESCRIPTION

Changes since BSP 03.44.0004:

General Stability/Exceptions/Crashes/Lockups

SPR24853 – Resolved an issue where the device would freeze on one of the bootup splash screens and fail to complete bootup, and would require a reload of the OS to function.

Note:

- The OS update package does not wipe the application folder. If it is preferred to wipe the Application folder during the OS update, the CleanAppl.bin command should be added to the pkgs.lst file. The CleanAppl.bin file is already included in the OS Update package.
- "Clean Boot" and "CleanBoot and Clean Application" packages have been updated ("ES400-MC65-CleanBoot&CleanBoot-Blank_v2.zip") for OS versions containing the Datalight FlashFX flash file system. The new packages are compatible with older OS versions as well.

CONTENTS

Hot_Fix_ES400_BSP44.1001EN.zip - Update Loader images for English OS 03.44.1001

405Bw65enAB3441001.apf- AirBeam Image for English OS 03.44.1001

DEVICE COMPATIBILITY

This software release has been approved for use with the following devices.

Device	Operating System	
ES405B	Windows Mobile 6.5.3	



INSTALLATION REQUIREMENTS

This software package has been approved for use with the following:

- Microsoft Windows 2000 or Windows XP Operating System
- ActiveSync 4.5 or higher.
- If developing applications for Windows Mobile 6.5
- ES405B currently running English Rev A BSP19.1, BSP19.11, MR1 BSP19.103, BSP 31.2,BSP 41.400,BSP 44.0000, 3.44.0004 and CPLD 13.1

INSTALLATION INSTRUCTIONS

Copy contents of zip file to SD card or to \Temp folder. Execute StartUpdLdr.exe or cold boot terminal by pressing 1 + 9 + pwr and hold the left trigger key to start the update loader process.

PART NUMBER AND RELEASE DATE

Hot_Fix_ES400_BSP44.1001EN.zip May 09, 2014 405Bw65enAB3441001.apf July 22, 2014