

Customer Concierge (CC5000-10) Software Release Notes

Release 2.0.2.16 – Android Lollipop

Enterprise Visibility and Mobility Data Capture Solutions

Dec 20, 2017



# Copyright

This document contains proprietary and confidential information which is the property of Zebra Technologies Corporation and is furnished for the sole purpose of the operation and maintenance of Zebra Technologies products. No part of this publication is to be used for any other purpose or to be reproduced, copied, disclosed, transmitted, stored in a retrieval system or translated into any human or computer language in any form, by any means, in whole or in part, without the express written consent of Zebra Technologies.

Except as otherwise may be explicitly agreed to in writing, Zebra Technologies makes no representation that equipment, software programs and practices described herein will not infringe on existing or future patent rights, copyrights, trademarks, trade secrets or other proprietary rights of third parties. The descriptions contained herein do not imply the granting of license to make, use sell, license or otherwise transfer Zebra Technologies products described herein. Zebra Technologies disclaims responsibilities for errors which may appear in this document, and it reserves the right, in its sole discretion and without notice, to make subscriptions and modifications in the products and practices described in this document.

© 2017 Zebra Technologies Corporation



### Scope

This document covers release notes for the revision of CC5000-10 Concierge, v2.0.2.16.

# Supported Hardware Configurations

□ CC5000-10

### Verification of Hardware

Ensure that the hardware being used is a released unit with a serial number and other regulatory labels in place. Questions may be addressed to Zebra Technologies Tier One Support team (800-653-5350).

#### Overview

Customer Concierge, v2.0.1 is based on Android Lollipop AOSP v5.1.1. It also contains Zebra value add software to include MX, Data Wedge, The EMDK and the Fusion Wi-Fi Stack.

## SW Component Versions

- o TUT Level 4.16-CC5000
- MXMF 6.2.1.0
- OSX TI.51.5.2.2
- o Data-Wedge 86.2.23
- o EMDK 6.3.23.623
- Scanning Framework 16.0.52.1
- o Fusion -5.00.0.0.026

### Features

- o Zebra Fusion Update to comply EU Radio Equipment Directive, effective June 2017.
- Zebra MX API support
- Zebra EMDK API support
- o Zebra Fusion Integrated Wi-Fi
- Zebra Bluetooth Stack
- Zebra Stage Now included
- o Zebra Enterprise Home Screen support (v2.5 and later)
- Google CTS/GTS compliant.
- Latest Google Webview Toolkit used in browser (April 2017)
- Now signed with Zebra Mobility Common Keyset
- OTA Capability to upgrade Jellybean to Lollipop
- o OTA and Recovery Mode (SD Card) capability to upgrade Lollipop to a new version of Lollipop
- o Sample/generic upgrade MDZ available to users for Jellybean to Lollipop upgrade
- Fastboot upgradeable
- Supports ADB side load.



#### Hardware Limitations

The following list are the known issues at time of release related to the CC5000-10 hardware to include internal parts and external parts and ports

- If using an External SD Card for Recovery Mode, it must be inserted prior to power on or rebooting the device into Recovery Mode.
- Sleep/Suspend is not enabled on this device.
- Reset/Power button is disabled. Unit must be powered off through master power, or rebooted through API call, or user UI.

### Issues Addressed

- Outermost USB port cannot be used for external storage.
- o Inconsistency using Display Mirroring with an external monitor.
- o Persistency issue of the Host Name following a reboot.
- Device Encryption issue while connected to Wired Ethernet.

### Known Software Issues

- Encrypting the device (using the UI or through MDM such as AirWatch) is discouraged as it can affect performance.
- Some symbologies may not scan for the following reasons
  - They are too large.
  - o 1D barcodes that are stacked and extended in length over 3-4 lines.
  - QR Codes with nonstandard settings
  - Barcodes with poor resolutions.
  - Intermittent with some HanXin barcodes
- Applications cannot be moved to and from external device storage
- On Datawedge "Scan Params" Menu, Beep Volume can only be changed by adjusting notification volume, regardless of "source" selection.
- On Datawedge Scanner Beam timer works as set value + 5 seconds.
- o Browser Manger: Check Remember password doesn't work.
- o No headset notification icon coming up when you plugged in headset.
- o "Automatic screen lock" option not supported in this release.
- MX: Wi-Fi & Clock CSP setting changes done through MX API can only be seen after going back to settings main page and then again to the modules page.