
Release Notes – MC67NA WM6.5 BSP v06.57.14 - Enhanced USB driver to support KVL4000 accessory – SPR34400

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Release Date](#)

Introduction

SPR34400 - Updated USB driver to support KVL4000 accessories.

Description

Enhanced USB driver to support KVL4000 accessory.

Contents

SPR34400_MC67_NA_WM65_en_065714_v1_0_WB.cab (Hotfix package with auto Warm boot)

SPR34400_MC67_NA_WM65_en_065714_v1_0_NB.cab (Hotfix package without auto Warm boot)

Device Compatibility

This Hotfix package software release has been approved for use with the following Zebra devices,

Device	Operating System	BSP Version
MC67NA	WM 6.5	v06.57.14

Installation Requirements

This SW is intended for MC67NA WM 6.5 devices with OS v06.57.14

Installation Instructions

For Normal installation of the PATCH:

1. Copy "SPR34400_MC67_NA_WM65_en_065714_v1_0_WB.cab" file to the application folder/SD card on the device by using Microsoft Active Sync or Mobile Device Center.
2. Navigate on the device to the application folder/SD card.
3. Deploy the solution by tapping on the "SPR34400_MC67_NA_WM65_en_065714_v1_0_WB.cab" file.
4. After successful deployment of the "SPR34400_MC67_NA_WM65_en_065714_v1_0_WB.cab" file, device will do an automatic warm boot.

For MSP or REMOTE installation of the PATCH:

1. Set up MDM (MSP, Soti, Airwatch, etc..) to send "SPR34400_MC67_NA_WM65_en_065714_v1_0_NB.cab" file to the application folder of the device.
2. To deploy the solution, setup in MDM to install the cab file "SPR34400_MC67_NA_WM65_en_065714_v1_0_NB.cab" file.
3. Changes will take effect after a manual reboot of the terminal or if MDM reboots device.

Release Date

June 2018