
Release Notes - TC55 JB - BSP v01.74G.99.17 - Android Keyboard Gets Locked When Number Of Characters Entered Into A Text Box In Html File Reaches Maxlength Value - SPR 27600

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Part Number and Release Date](#)

Introduction

In TC55 JB, Android keyboard gets locked when number of characters entered into a text box in html file reaches maxlength value.

Description

The provided OTA package fixes the Android keyboard lock issue.

Contents

SPR27600_TC55_JB_en_1.74.99.17_GMS.zip - OTA package for GMS device

Device Compatibility

This software release has been approved for use with the following Zebra devices,

Device	Operating System	OEM Version
TC55	Android JB 4.1.2	v01.74G.99.17

Installation Requirements

This SW is intended for the TC55 device running GMS 01.74G.99.17 build only.

Installation Instructions

1. Connect the USB cable from your PC to the device and enable USB mass storage mode on the device.
2. On your PC you should see an internal and external USB mass storage drive (SD card) appears in the File Explorer and copy the recovery update zip file to any storage.
3. Press and hold on the device Power button, Scan/Action button and Vol+ until the screen is turned OFF.

4. Release the Power and Scan/Action buttons and continue to hold Vol+ button.
5. The device should enter into Recovery update mode.
6. Release Vol+.
7. Click on Vol+ or Vol- to navigate and select appropriate storage.
8. Click on Scan/Action button to select the option.
9. Click on Vol+ or Vol- to navigate to the recovery update zip file.
10. Click on Scan/Action button to select the recovery update zip file.
11. Device will automatically reboot and will be ready to use.

Part Number and Release Date

N/A
June, 2015