



Release Notes – Zebra Android 13

13-26-13.00-TG-U00-STD-NEM-04 Release (GMS)

Highlights

This Android 13 GMS release 13-26-13.00-TG-U00-STD-NEM-04 covers the MC3400, MC9400, MC9450, PS30, TC53e, TC58e, WT5400 and WT6400 family of products.

Please see device compatibility under the Addendum section for more details.

Software Packages

Package Name	Description
NE_FULL_UPDATE_13-26-13.00-TG-U00-STD-NEM-04	Full package update
NE_DELTA_UPDATE_13-24-08.00-TG-U00-STD_TO_13-26-13.00-TG-U00-STD.zip	Delta update package from 13-24-08.00-TG-U00
NE_DELTA_UPDATE_13-24-19.00-TG-U00-STD_TO_13-26-13.00-TG-U00-STD.zip	Delta update package from 13-24-19.00-TG-U00 (Only for TC58e)

Security Updates

This build is compliant up to [Android Security Bulletin](#) of February 01, 2025.

LifeGuard Update 13-26-13.00-TG-U00

○ New Features

- **Restriction for skip setup wizard**

- Due to new mandatory privacy requirements from Google, the Setup Wizard Bypass feature has been discontinued on devices running Android 13 and later. Consequently, it is now restricted to skip the Setup Wizard screen, and the StageNow barcode will not function during the Setup Wizard, displaying a toast message stating “Not supported.”
- If the Setup Wizard has already been completed and its data was configured to persist on the device in the past, there is no need to repeat this process following an Enterprise Reset.
- For more details, please refer to the Zebra FAQ documentation:
<https://techdocs.zebra.com/zebradna/latest/faq/#setupwizardsuw>

- **MX 14.1**

- **Access Manager** adds the ability to:
 - Control device-user access to the Zebra RxLogger diagnostics utilit on the device.
- Skip Set up wizard no longer supported in first boot and setup wizard needs to be configured manually.
- **MX 14.0**
 - **Access Manager** adds the ability to:
 - Individually control device-user access to Accessibility and Network settings in the Android Settings panel.
 - **App Manager** adds the ability to:
 - Use the App Feature parameter to automatically launch an app or reboot the device after installation.
 - **Display Manager** adds the ability to:
 - Control the Secondary Monitor Auto-rotation when a device is placed in a cradle connected to a monitor.
 - Specify a video file(MP4) in the Screen Saver Path for display on the device.
 - **UI Manager** adds the ability to:
 - Select a Navigation Method for switching between screens on a device.
 - Control Color Inversion on the device.
 - Control TalkBack feature, which speaks words displayed on the device screen.
- **Bluetooth**
 - Admin support to control BT Profile enable or disable
- **KeyEvent**
 - Added support to combine key remapping and double trigger mapping to single barcode.
 - Added support to remap a key with flashlight application
- **RxLogger**
 - Added the Persist Logging option in the Logcat module.
- **Audio**
 - Enhanced the functionality for the MDM to control mute usage and vibrate usage
- **Scanner**
 - French language support in Bluetooth Pairing Utility
 - Expanded OCR-A and OCR-B support to include camera as input, in addition to the existing scan engine capabilities.
 - New, larger green crosshair for all data capture viewfinders, designed for improved visibility and enhanced accessibility.

○ Resolved Issues

- SPR-54231: Updated log information reported in RxLogger.
- SPR-55047: Resolved an Issue to support A11 to A13 persistence
- SPR-55297: Resolved an issue to handle special characters in user input data
- SPR-55637: Resolved an in issue where in TC58e was loosing of WWAN connection through eSim in customer app.
- SPR-54871: Resolved an issue wherein device fails to connect back to network after the battery is removed for a day.
- SPR-55344: Resolved the Touch Panel Unresponsive Issue during device suspend/resume with lock screen to None.

○ Usage Notes

- None

LifeGuard Update 13-24-19.00-TG-U00(Only for TC58E)

○ New Features

- This release supports the TC58e Secure Element SKU (Google StrongBox feature).

LifeGuard Update 13-24-08.00-TG-U00

○ New Features

• MxProxy

- Schedule a screen saver to automatically activate on specified day(s) and time(s).
- UI Manager adds the ability to:Select an auto-fill service to use when automatically filling in text fields.
- App Manager adds the ability to:Manage app widgets through the App Feature Action parameter.

ZDM

- Configure an external monitor to automatically set optimal resolution based on its native capabilities.
- Set the External Monitor Orientation to use when auto-rotation is disabled.
- Allocate device storage for use as system RAM.

DataWedge

- Added support for RegEx rules generation in Free-Form OCR and Picklist+OCR.
- Added support for export/import configurations to/from a public folder in DataWedge
- Added support for custom delimiters (alphanumeric) under the "Data Formatting & Ordering" section under UDI Specific, GS1 specific, Multibarcodes Specific and Workflow specific workflows.
- Added support for parenthesis around AI under the "Data Formatting & Ordering" section under UDI Specific, GS1 specific.

• Audio

- Microphone On/Off – This is the On/Off switch for the device microphone, which controls audio input through connected audio device.

• WLAN

- Added Support for 802.1x cabled connections.

• Scanner

- Custom & Resizable Region of Interest for Free-Form OCR
- Integrate Rev B firmware for SE58 Scan Engine [PAAFXS00-002-R02]

• Camera

- Added support for new camera driver for 16MP rear camera module on MC9400/MC9450 products.

○ Resolved Issues

- SPR-53585 - Control USB rules in case of application changed or removed.
- SPR-54018 - Datawedge switch param API is not working as expected when hardware trigger is disabled.
- SPR-54309 - Diamond key should not print any symbols if the input type of the focused view is number.
- SPR-54624 - aimer is not shown under Free-Form image capture has been enabled

- SPR-53808 - Failed to decode Enhanced dot matrix barcode, Expose the Datamatrix Inverse Setting
- SPR-54026 - EMDK Barcode parameters for 2D inverse
- SPR-54264 - Snap on trigger not working when DS3678 is connected
- SPR-54043 - Scanner changes, Active Index should not be reset if clear submit failed
- SPR-54105 - DS8178 USB cradle unable to scan with latest FW

○ Usage Notes

- Devices with the new camera module cannot be downgraded – the minimum build requirement is 13-24-08.00-TG-U00-STD-NEM-04 on A13 or newer.
- To identify the new camera type user can check 'ro.boot.device.cam_vcm' using getprop from the adb. Only new camera devices will have the below property:
ro.boot.device.cam_vcm=86021

LifeGuard Update 13-23-07.00-TG-U00 (TC53e, TC58e)

○ New Features

- Secure Element SKU (Google StrongBox feature) support for TC53E.
- DHCP Option 119 is supported in this release.

○ Resolved Issues

- SPR-53899 - Resolved an issue where System restricted with Reduced Accessibility still allows users to access and edit all application permissions, using Privacy Indicators
- SPR-53777 - Resolved an issue EHS System restricted with Reduced Accessibility still allows users to access and edit all application permissions.
- SPR-53473 - Resolved an issue where Home button stops working on uninstalling ELS while in foreground.
- SPR-53434 / SPR-54044 – Resolved an issue where External Display Resolution gets reset when docked.
- SPR-53388 - Firmware Update for SE55 Scan Engine with Critical bug fixes, and performance enhancements. This update is highly recommended.
- SPR-54454 – Resolved the Touch Panel sluggish/unresponsive issue after device suspend/resume cycle.

○ Usage Notes

- None

LifeGuard Update 13-21-20.00-TG-U05

○ New Features

- None

○ Resolved Issues

- None

- **Usage Notes**

- None

LifeGuard Update 13-21-20.00-TG-U00

- **New Features**

- Desktop Mode Solution support on TC5x devices with WorkStation Cradles.
- Verizon support on TC58e.
- DHCP Option 119 is supported in this release.

- **Resolved Issues**

- SPR-53899 - Resolved an issue where System restricted with Reduced Accessibility still allows users to access and edit all application permissions, using Privacy Indicators
- SPR-53777 - Resolved an issue EHS System restricted with Reduced Accessibility still allows users to access and edit all application permissions.
- SPR-53473 - Resolved an issue where Home button stops working on uninstalling ELS while in foreground.
- SPR-53434 / SPR-54044 – Resolved an issue where External Display Resolution gets reset when docked.
- SPR-53388 - Firmware Update for SE55 Scan Engine with Critical bug fixes, and performance enhancements. This update is highly recommended.

- **Usage Notes**

- None

LifeGuard Update 13-20-13.00-TG-U00

- **New Features**

- Products Supported
 - First SW release in Android 13 to support TC53e RFID SKUs.
- DHCP Option 119 is supported in this release.

- **Resolved Issues**

- SPR-53899 - Resolved an issue where System restricted with Reduced Accessibility still allows users to access and edit all application permissions, using Privacy Indicators.
- SPR-53777 - Resolved an issue EHS System restricted with Reduced Accessibility still allows users to access and edit all application permissions.
- SPR-53473 - Resolved an issue where Home button stops working on uninstalling ELS while in foreground

- **Usage Notes**

- None

LifeGuard Update 13-19-22.00-TG-U00

- **New Features**

- This is the first Android 13 GMS release for MC3400 family of products.

- **Resolved Issues**

- None

- **Usage Notes**

- None

LifeGuard Update 13-18-07.00-TG-U00

- **New Features**

- This is the first Android 13 GMS release for WT5400 and WT6400 family of products.

- **Resolved Issues**

- None

- **Usage Notes**

- None

LifeGuard Update 13-18-13.00-TG-U00

- **New Features**

- Products Supported.
 - First SW release in Android 13 for TC58e.
 - Support added for WT6400 keypad SKUs.
- StayLinked SmartTE client is pre-installed on MC9400 and MC9450
- Enhanced support for Android COPE (corporate-owned, personally enabled) mode. Details published soon on Zebra Techdocs.

- **Resolved Issues**

- SPR51755 - Resolved an issue where Bluetooth HID devices were getting disabled when USB module usage is disabled.
- SPR48680 – Resolved an issue where video conference over WEB RTC (Real Time Communication) interpreting solution was not working.
- SPR40250 – Resolved an issue where power off option in power menu is blocked when the automation test is running.
- SPR51853 – Resolved an issue where key value was coming wrong for SYS RQ [ctrl + k].
- SPR51755 – Resolved an issue where Settings Manager can still access notifications after disabling access.
- SPR51855 - Resolved an issue where device reboots are happening randomly on WSC cradle or with WSC cradle disconnections.
- SPR53616 - Resolved an issue where vibrate icon does not show in Status Bar.

- SPR53473 - Resolved an issue where Home Button stops working on uninstalling Identity Guardian application.
- SPR52786 - Resolved an issue where Verizon IOT data only sim does not get activated.
- SPR53368 - Resolved an issue where esim activation failing in GMS Restricted mode.
- SPR53225 - Resolved an issue where Network Connection Manager does not prioritize Wifi profiles in a correct manner.

- **Usage Notes**

- None

LifeGuard Update 13-15-17.00-TG-U04

- **New Features**

- This is the first Android 13 GMS release for MC3400 family of products.

- **Resolved Issues**

- None

- **Usage Notes**

- None

LifeGuard Update 13-16-30.00-TG-U00

- **New Features**

- This is the first Android 13 GMS release for PS30 family of products.

- **Resolved Issues**

- This is the first Android 13 GMS release for PS30 family of products.

- **Usage Notes**

- None

LifeGuard Update 13-15-17.00-TG-U00

- **New Features**

- **Products Supported**
 - First SW release in Android 13 for MC9450 and TC53e
 - Support added for MC9400 Freezer SKUs
 - Support added for BLE Batteries in MC9400 / MC9450
- **Zebra Wireless Analyzer.**
 - Zebra Wireless Analyzer and Wireless Insights are supported in this release.
- **MX**

- Added a new MX feature which allows to show/hide the active apps panel which appears on Notification Panel UI
- Added new MX feature to enable/disable write access to Android/data and Android/obb folders of the device, when connected via MTP.
- Added a new MX feature which allows admin to show/hide the Remote Cast/Control icon in status bar when device is remotely controlled.
- Added a new MX feature which allows admin to show/hide Keyguard screen on remote display.

○ Resolved Issues

- SPR51755 - Resolved an issue where Bluetooth HID devices were getting disabled when USB module usage is disabled.
- SPR48680 – Resolved an issue where video conference over WEB RTC (Real Time Communication) interpreting solution was not working.
- SPR40250 – Resolved an issue where power off option in power menu is blocked when the automation test is running.
- SPR51853 – Resolved an issue where key value was coming wrong for SYS RQ [ctrl + k].
- SPR51755 – Resolved an issue where SettingsMgr can still access notifications after disabling access

○ Usage Notes

- None

LifeGuard Update 13-11-22.00-TG-U05

○ New Features

- Products Supported.
 - First SW release in Android 13 for MC9450 and TC53e
 - Support added for MC9400 Freezer SKUs
 - Support added for BLE Batteries in MC9400 / MC9450
- Zebra Wireless Analyzer
 - Zebra Wireless Analyzer and Wireless Insights are supported in this release.
- MX
 - Added a new MX feature which allows to show/hide the active apps panel which appears on Notification Panel UI.
 - Added new MX feature to enable/disable write access to Android/data and Android/obb folders of the device, when connected via MTP
 - Added a new MX feature which allows admin to show/hide the Remote Cast/Control icon in status bar when device is remotely controlled.
 - Added a new MX feature which allows admin to show/hide Keyguard screen on remote display.

○ Resolved Issues

- SPR51755 - Resolved an issue where Bluetooth HID devices were getting disabled when USB module usage is disabled.

- SPR48680 – Resolved an issue where video conference over WEB RTC (Real Time Communication) interpreting solution was not working
- SPR40250 – Resolved an issue where power off option in power menu is blocked when the automation test is running
- SPR51853 – Resolved an issue where key value was coming wrong for SYS RQ [ctrl + k]
- SPR51755 – Resolved an issue where SettingsMgr can still access notifications after disabling access

○ Usage Notes

- None

LifeGuard Update 13-11-22.00-TG-U00

○ New Features

- Support added for 6GHz band.
- Support added for the SE58 scanner devices.
- Support added for the 5MP resolution for rear facing camera.

○ Resolved Issues

- Issue with back button when a text field is highlighted in certain apps, is fixed in this release.
- Issues with Auto PAC Proxy feature is resolved, and feature is enabled.

○ Usage Notes

- None

LifeGuard Update 13-10-03.00-TG-U00

○ New Features

- This is the first Android 13 GMS release for MC9400 family of products.
- Initial Beta Release of Zebra Showcase App (Self Updatable) explores the latest features and solutions, a platform for new demos built on Zebra Enterprise Browser.
- DWDemo has moved to ZConfigure folder.

○ Resolved Issues

- None

○ Usage Notes

- None

Version Information

Below table contains important information on versions

Description	Version
-------------	---------

Product Build Number	13-26-13.00-TG-U00-STD-NEM-04
Android Version	13
Security Patch level	February 01, 2025
Component Versions	Please see Component Versions under Addendum section

Device Support

This release supports the MC3400, MC9400, MC9450, PS30, TC53e, TC58e, WT5400 and WT6400.

Please see device compatibility details under Addendum Section.

Known Constraints

- Delta OTA packages are not supported in Recovery mode. To apply Delta OTA packages, use StageNow/MDM solution.
- Zebra DHCP options is not supported on all 3rd party ethernet dongles.
- NFC Host card emulation (HCE) feature is not supported in this SW release of TC58e and PS30. The feature will be enabled in future Android 13 releases.
- 4K video resolution is not supported on this SW release, using the native video player.
- StayLinked SmartTE client can only be upgraded via the client distributed directly from StayLinked Corporation. Play Store version cannot be installed over it.

Important Links

- [Installation and setup instructions](#) (If the link does not work, please copy it to browser and try)
- [Zebra Techdocs](#)
- [Developer Portal](#)

Addendum

Device Compatibility

This software release has been approved for use on the following devices.

Device Family	Part Number		Device Specific Manuals and Guides
MC9400	MC9401-0G1J6BSS-A6 MC9401-0G1J6CSS-A6 MC9401-0G1J6CSS-NA MC9401-0G1J6DSB-TR	MC9401-0G1P6DSB-TR MC9401-0G1P6DSS-A6 MC9401-0G1P6DSS-NA MC9401-0G1P6DSS-TR	MC9400

	MC9401-0G1J6DSS-A6 MC9401-0G1J6DSS-IN MC9401-0G1J6DSS-NA MC9401-0G1J6DSS-TR MC9401-0G1J6ESS-A6 MC9401-0G1J6ESS-IN MC9401-0G1J6ESS-NA MC9401-0G1J6GSS-A6 MC9401-0G1J6GSS-NA MC9401-0G1J6HSS-A6 MC9401-0G1J6HSS-NA MC9401-0G1M6ASS-A6 MC9401-0G1M6BSS-A6 MC9401-0G1M6CSB-A6 MC9401-0G1M6CSS-A6 MC9401-0G1M6CSS-NA MC9401-0G1M6DSB-A6 MC9401-0G1M6DSB-NA MC9401-0G1M6DSS-A6 MC9401-0G1M6DSS-IN MC9401-0G1M6DSS-NA MC9401-0G1M6ESB-NA MC9401-0G1M6ESS-A6 MC9401-0G1M6ESS-NA MC9401-0G1M6GSB-NA MC9401-0G1M6GSS-A6 MC9401-0G1M6GSS-NA MC9401-0G1M6HSS-A6 MC9401-0G1M6HSS-NA MC9401-0G1P6DSB-A6 MC9401-0G1P6DSB-NA	MC9401-0G1P6GSS-A6 MC9401-0G1R6ASS-A6 MC9401-0G1R6BSS-A6 MC9401-0G1R6BSS-NA MC9401-0G1R6CSS-A6 MC9401-0G1R6DSB-NA MC9401-0G1R6DSS-A6 MC9401-0G1R6DSS-NA MC9401-0G1R6ESS-NA MC9401-0G1R6GSS-A6 MC9401-0G1R6GSS-NA MC9401-0G1R6HSS-A6 MC9401-0G1R6HSS-NA MC9401-0G1J6DCS-A6 MC9401-0G1J6DCS-NA MC9401-0G1M6BCS-A6 MC9401-0G1M6CCS-A6 MC9401-0G1M6CCS-NA MC9401-0G1M6DCS-A6 MC9401-0G1M6DCS-NA MC9401-0G1M6HCS-NA MC9401-0G1J6DNS-NA MC9401-0G1J6ENS-NA MC9401-0G1M6CNS-NA MC9401-0G1M6DNS-NA MC9401-0G1M6ENS-NA MC9401-0G1M6GNS-NA MC9401-0G1P6ENS-FT MC9401-0G1R6CNS-NA MC9401-0G1R6ENS-NA MC9401-0G1M6DNS-A6	
MC9450	MC945A-3G1J6CSS-NA MC945A-3G1J6DSS-NA MC945A-3G1J6ESS-NA MC945A-3G1J6GSS-NA MC945A-3G1J6HSS-NA MC945A-3G1M6CSS-NA MC945A-3G1M6DSB-NA MC945A-3G1M6DSS-NA MC945A-3G1M6ESB-NA MC945A-3G1M6ESS-NA MC945A-3G1M6GSB-NA MC945A-3G1M6GSS-NA MC945A-3G1M6HSS-NA MC945A-3G1P6DSB-NA MC945A-3G1P6DSS-NA MC945A-3G1R6BSS-NA MC945A-3G1R6DSB-NA MC945A-3G1R6DSS-NA MC945A-3G1R6ESS-NA MC945A-3G1R6GSS-NA MC945A-3G1R6HSS-NA MC945A-3G1M6DSS-FT MC945B-3G1J6BSS-A6 MC945B-3G1J6CSS-A6	MC945B-3G1J6DSS-A6 MC945B-3G1J6ESS-A6 MC945B-3G1J6GSS-A6 MC945B-3G1J6HSS-A6 MC945B-3G1M6ASS-A6 MC945B-3G1M6BSS-A6 MC945B-3G1M6CSB-A6 MC945B-3G1M6CSS-A6 MC945B-3G1M6DSB-A6 MC945B-3G1M6DSS-A6 MC945B-3G1M6DSS-TR MC945B-3G1M6ESS-A6 MC945B-3G1M6GSS-A6 MC945B-3G1M6HSS-A6 MC945B-3G1P6DSB-A6 MC945B-3G1P6DSS-A6 MC945B-3G1P6DSS-TR MC945B-3G1P6GSS-A6 MC945B-3G1R6ASS-A6 MC945B-3G1R6BSS-A6 MC945B-3G1R6CSS-A6 MC945B-3G1R6DSS-A6 MC945B-3G1R6GSS-A6 MC945B-3G1R6HSS-A6	MC9450

PS30J	PS30JB-0H1A600 PS30JB-0H1NA00	PS30JP-0H1A600 PS30JP-0H1NA00	PS30
WT5400	WT0-WT54B-T6DAC1NA WT0-WT54B-T6DAE1NA	WT0-WT54B-T6DAC1A6 WT0-WT54B-T6DAE1A6	WT5400
WT6400	WT0-WT64B-T6DCC2NA WT0-WT64B-T6DCE2NA WT0-WT64B-K6DCC2NA WT0-WT64B-K6DCE2NA	WT0-WT64B-T6DCC2A6 WT0-WT64B-T6DCE2A6 WT0-WT64B-K6DCC2A6 WT0-WT64B-K6DCE2A6	WT6400
MC3400	MC3401-0G1D43SS-NA MC3401-0G1K43SS-NA MC3401-0G1J54SS-NA MC3401-0G1M54SS-NA MC3401-0G1J53SS-NA MC3401-0G1P64SS-NA MC3401-0G1M53SS-NA MC3401-0G1R64SS-NA MC3401-0G1P63SS-NA MC3401-0G1R63SS-NA MC3401-0G1D43SS-NA01 MC3401-0G1D43SS-IN MC3401-0G1K43SS-IN MC3401-0G1J53SS-IN MC3401-0G1J54SS-IN MC3401-0G1M53SS-IN MC3401-0G1M54SS-IN MC3401-0G1P63SS-IN MC3401-0G1R63SS-IN MC3401-0G1D43SS-IN01	MC3401-0G1D42SS-A6 MC3401-0G1D43SS-A6 MC3401-0G1K42SS-A6 MC3401-0G1K43SS-A6 MC3401-0G1J52SS-A6 MC3401-0G1J53SS-A6 MC3401-0G1J54SS-A6 MC3401-0G1M52SS-A6 MC3401-0G1M53SS-A6 MC3401-0G1M54SS-A6 MC3401-0G1P62SS-A6 MC3401-0G1P63SS-A6 MC3401-0G1P64SS-A6 MC3401-0G1R62SS-A6 MC3401-0G1R63SS-A6 MC3401-0G1R64SS-A6 MC3401-0G1D43SS-A601 KT-MC3401-0G1D42SS-A6 KT-MC3401-0G1D43SS-A6 MC3401-0G1D43SS-TR MC3401-0G1K43SS-TR MC3401-0G1J53SS-TR MC3401-0G1M53SS-TR MC3401-0G1P63SS-TR MC3401-0G1R63SS-TR KT-MC3401-0G1D43SS-TR	MC3400
TC53e	TC530E-0T1E1B1000-NA TC530E-0T1K1B1000-NA TC530E-0T1K6B1000-NA TC530E-0T1E1B1B00-NA TC530E-0T1E1B1000-A6 TC530E-0T1E6B1000-A6 TC530E-0T1K6B1000-A6 TC530E-0T1K7B1B00-A6 TC530E-0T1E6B1B00-A6 TC530E-0T1K1B1000-A6	TC530R-0T1E1B1000-US TC530R-0T1E1B1000-EA TC530R-0T1E1B1000-RW TC530R-0T1K7B1B00-US TC530R-0T1K7B1B00-US01 TC530E-0T1E1B1000-TR TC530E-0T1E1B1001-NA TC530E-0T1E1B1001-A6	TC53e

TC58e	TC58BE-3T1E1B1A80-A6 TC58BE-3T1E6B1A80-A6 TC58BE-3T1J6B1A80-A6 TC58BE-3T1J6B1E80-A6 TC58BE-3T1K6B1A80-A6 TC58BE-3T1K7B1E80-A6 TC58BE-3T1J6B1W80-A6	TC58AE-3T1E1B1A10-NA TC58AE-3T1J1B1A10-NA TC58AE-3T1J1B1A11-NA TC58AE-3T1K6B1A10-NA TC58AE-3T1K6B1A11-NA	TC58e
-------	--	--	-----------------------

Component Versions

Component / Description	Version
Linux Kernel	5.10.218-android12-9-00028-g8c6f0fce67e3-ab130 #1 Tue Jan 28 11:33:42 UTC 2025
AnalyticsMgr	10.0.0.1008
Android SDK Level	33
Audio (Microphone and Speaker)	Vendor: 0.48.2.0 ZQSSI: 0.19.0.0
Battery Manager	1.5.4
Bluetooth Pairing Utility	6.8
Zebra Camera App	2.5.11
DataWedge	14.3.2
EMDK	13.0.30.4730
Files	14-11467625
License Manager and LicenseMgrService	License Manager : 6.1.4 License Agent Version: 6.3.9.5.0.3
MXMF	14.1.0.7
NFC and NFC FW	MC94x: NFC - PN7160_AR_13.21.00 and MC9450 FW - 12.50.9 MC9400 FW - 12.50.9 PS30JP:NA WT5400/WT6400: NFC - PN7221_AR_13.21.00 FW - 12.50.9

	MC3400: NFC - PN7221_AR_13.21.00 FW - 12.50.9
OEM info	9.0.1.257
OSX	QCT4490.130.13.23.16
Rxlogger	13.0.12.82
Scanning Framework	42.37.29.0
StageNow and Zebra Device Manager	13.4.0.0 and 14.1.0.7
WLAN	Version: FUSION_QA_6_1.5.0.006_T Firmware Version: 1.1.5.0.444.4 HW:QCA6490
WWAN Baseband version	MC9400 - NA MC9450 - Z250117A-1_191.1a-00165 PS30 - NA WT5400/WT6400 - NA
Zebra Bluetooth	13.9.0
Zebra Volume Control3	3.0.0.111
Zebra Data Service	10.0.9.1032
Velocity ATTE	MC3400/MC94x: 2.1.37.24157.b6be375 PS30, WT5400, WT6400 - NA
SmartTE	MC3400/MC94x: 15.05.0260 PS30, WT5400, WT6400 - NA
Wireless Analyzer App Version	WA_A_3_2.2.0.014_T App Version: 3.2.19

Revision History

Rev	Description	Date
1.0	Initial release	February 14, 2025