

Installation Instructions for Scanner holder for MT3611-10 (Part No.: 9012951) & MT3611-12 (Part No.: 9016915)

CAUTION Ensure correct mounting during installation. Psion expressly points out that it does not assume any responsibility for incorrect and faulty installation.



Fig1.

Fig 2. and Fig 3 illustrate the scanner holder assembled. Compose the holder first as shown in the images



Fig2.

Installation Instructions for Scanner holder for MT3611-10 (Part No.: 9012951) & MT3611-12 (Part No.: 9016915)



Fig3.

The holder is attached to the terminal according to Fig 4.




Fig4.