



Motion Computing Software Release Note

Name	STMicroelectronics Accelerometer Sensor Driver for Windows 7
File Name	Accelerometer_1.7.11.6.zip
Release Date	July 13, 2012
This Version	1.7.11.6
Replaces Version	All previous versions
Intended Users	Motion CL910 users
Intended Product	Motion CL910 Tablet PCs ONLY
File Size	3.2 MB
Supported Operating System	Windows 7

Fixes in this Release

- NA

What's New In This Release

- Initial release.

Known Issues and Limitations

- NA

Installation and Configuration Instructions

To install Sensor 1.7.11.6, perform the following steps:

1. Download the update and save to the directory location of your choice.
2. Unzip the file to a location on your local drive.
3. In Device Manager, within Sensors, select to update the "STMicroelectronics 6-Axis Accelerometer/Magnetometer" driver and point to the location where you unzipped the file in step 2.

Licensing

Refer to your applicable end-user licensing agreement for usage terms.