



## Motion Computing Software Release Note

Name	<b>Intel Wireless LAN Driver for Windows 7</b>
File Name	<b>Intel_Wireless_32-bit_17.13.11.zip</b>
Release Date	January 20, 2015
This Version	17.13.11 (Driver version 15.13.0.2)
Replaces Version	All previous versions
Intended Users	<b>Motion CL910 users</b>
Intended Product	Motion CL910 Tablet PCs ONLY
File Size	89 MB
Supported Operating System	Windows 7 (32-bit)

### Fixes in this Release

- Adhoc connect following power management event
- Mixed Mode Protection
- BSOD during power management events and WHCK test
- Intermittent Wi-Fi icon "x" after resume from Sleep
- Slow to connect after resume from Sleep
- Rx performance
- Unable to disable wireless after resume from Sleep

### What's New In This Release

- N/A

### Known Issues and Limitations

- BTHS is not installed on new installations starting with 17.0. Upgrades for existing 3160/7260 are supported

### Installation and Configuration Instructions

**To install WLAN 17.13.11, perform the following steps:**

1. Download the update and save to the directory location of your choice.
2. Unzip the file to a location on your local drive.
3. Double-click the installer (setup.exe) and follow the prompts.

### Licensing

Refer to your applicable end-user licensing agreement for usage terms.