



## Motion Computing Software Release Note

Name	<b>J3500 Button Driver for XP and Windows 7</b>
File Name	<b>J3500_ButtonDriver32_4410.zip</b> <b>J3500_ButtonDriver64_4410.zip</b>
Release Date	October 13, 2010
This Version	4.4.1.0
Replaces Version	All previous versions
Intended Users	<b>Motion J3500 users</b>
Intended Product	Motion J3500 Tablet PCs <b>only</b>
File Size	667 KB (32-bit), 672 (64-bit)
Supported Operating System	<ul style="list-style-type: none"><li>Windows XP Tablet Edition 2005, Version 2002, Service Pack 2 or Service Pack 3 - Installed.</li><li>Windows 7 (32-bit/64-bit), all versions.</li></ul>

### Fixes in this Release

- Fixed Chkdsk autorun on restart issue.
- Fixed occasional button mapping dropout on Windows 7.

### Known Issues and Limitations

Installing this update will reset the buttons to the default settings.

### Installation and Configuration Instructions

To install this version update, perform the following steps:

1. Download the update to the directory location of your choice.
2. Unzip the file to a location on your local drive.
3. Double-click on the installer and follow the prompts.
4. The driver is also available on Windows Update.

### Licensing

Refer to your applicable end-user licensing agreement for usage terms.