



Xplore Technologies Software Release Note

| | |
|----------------------------|---------------------------------------|
| Name | Xplore System Monitor Software |
| File Name | xSysMonSetup_2.2.0.1.zip |
| Release Date | September 19, 2018 |
| This Version | 2.2.0.1 |
| Replaces Version | All previous versions |
| Intended Product | L10 Platform |
| File Size | 838 KB |
| Supported Operating System | Windows 10 |

Fixes in this Release

- Fixes issue with warning message display

What's New in this Release

- N/A

Pre-requisites

- Requires L10 Physical Button Driver 4.7.0.1

Installation and Configuration Instructions

To install the System Monitor software 2.2.0.1 update, perform the following steps:

1. Download the update and save to the directory location of your choice.
2. **Uninstall** any previously installed **xSysMon** through **Control Panel → Programs and Features**
3. Unzip the file to a location on your local drive.
4. Double-click the installer (xSysMonSetup.msi) and follow the prompts.

Licensing

Refer to your applicable end-user licensing agreement for usage terms.